0/168

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/NDZ/2025/ 1310

Dated:-3/107/2025

To

Sh. Subhash Mittal (Secretary), Deepshikha Building, Plot no. 08, Rajendra Place, New Delhi -01.

Sub: Application for renewal of fire safety certificate in respect of Deepshikha Building, Plot no. 08, Rajendra Place, New Delhi -01.

Sir,

This has reference to your mail id sma.net.in dated 28.06.2025, on the subject cited above. In this regard, it is to inform you that the site was visited by officers concerned of this department on dated 22.07.2025 in presence of Mr. Avdesh Kumar and observed that shortcomings issued earlier vide letter no. F6/DFS/MS/NDZ/2025/243 dated 30/05/2025, have not been complied in toto so far and work is under progress. Further, trimming of tree is also required to ensure unobstructed access for fire tenders in case of emergency.

In view of above, FSC can't be renewed till the compliance of all the shortcomings at the earliest. Therefore, you are requested to rectify all the shortcomings at the earliest for further consideration in the matter. Further, the occupancy of the building/premises in absence of requisite fire safety arrangements shall be at risk and liability of owner/occupier

Yours faithfully,

Encl: As above.

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service



Copy to:

 The joint Director (building) C&I, DDA Building Section, DDA, Vikas Sadan, INA, New Delhi.

0124

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/NDZ/2025/ 243

Dated:-3 0.05.2025

To

Sh. Subhash Mittal (Secretary), Deepshikha Building, Plot no. 08, Rajendra Place, New Delhi -01.

Sub:- Regarding renewal of Fire Safety Certificate in r/ Deepshikha Building, Plot no. 08, Rajendra Place, New Delhi -01.

Sir,

This has reference to your letter no. nil dated nil & DFS Diary no.1248 dated 02/05/2025, on the subject cited above. In this regard, it is to inform that the site was inspected by the officers concerned of this department on 19/05/2025 in the presence of Manager and the following shortcomings were observed:-

- 1. Fire check doors found removed and broken at some floors and door closer also found removed.
- 2. Detector found nonfunctional at some floors.
- 3. Smoke management system in basement not provided.
- 4. Hose reel found removed at some floors.
- 5. MCP found nonfunctional
- 6. PA system is not audible properly

In view of above shortcomings, the application of renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at risk and liability of owner/occupier. The licensing /statuary authority may take suitable necessary action as deemed fit.

Yours

DIRECTOR Hi Fire Service

Copy to:

1. The Joint Director (building) C&I, DDA Building Section, DDA, Vikas Sadan, INA, New Delhi.