

c-2

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/NDZ/2025/ 574

Dated: 04 / 07 / 2025

To

The Principal,
Delhi Sport School,
04, Shamnath Marg, Civil Lines, Delhi - 54.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o **Delhi Sport School** located at
04, Shamnath Marg, Civil Lines, Delhi - 54.

Sir,

This is in reference to your letter outdoor diary No. 2490 dated 06.06.2025 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 01.07.2025 and observed that the shortcomings intimated vide letter of even No.F6/DFS/MS/2025/School/529 dated 18.06.2025 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Encl: As above.

Yours faithfully,


(Atul Garg)
Director

Delhi Fire Service
Tel: 011-23414000

o/c 8/2/27
10



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2025/School/ 529

Dated: 18/06/2025

To

The Principal,
Delhi Sport School located at
04, Shamnath Marg, Civil Line, Delhi-54.
principaldelhisportsschool@gmail.com

Sub: Regarding issuance of fire safety certificate in r/o Delhi Sport School (School ID No-1207266) located at 04, Shamnath Marg, Civil Line, Delhi-110054.

Sir,

Please refer to your received through online e-mail dated: 27/05/2025 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 11/06/2025 to verify the fire safety measures issued vide NBC Part-IV/UBBL-2016 and observed that the building was comprised of 01 New Academic Block, comprised of ground & 03 upper floors only. At the time of inspection Sh. Mulk Raj (Principal) was also present at site. During the course of inspection observations/ shortcomings made are as under:-

- 1 Hose reel hose is provided but not functional.
- 2 Terrace level fire fighting pump capacity of 450 lpm is provided but found not functional.
- 3 Standby power supply is not provided.
- 4 Electrical panel below staircase at academic block needs to be removed/shifted in a safer place.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of buildings is at your own risk & responsibility.

Yours faithfully

(Atul Garg)
Director

Ph: 011-23414000

9/6/25