

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI -110001

Dated: 26/06/2019

NO. F.6/DFS/MS/2024/ / 386

To,

Anup Singh, Under Secretary to the Government of India, Ministry of Finance, (Department of Revenue). (email:-singh.anup@nic.in)

Sub: Request for Fire NOC in r/o P.No.14, HUDCO Vishal Building, Bhikaji Cama Place, R.K. Puram, New Delhi- 110066

Sir,

This has a reference to your letter No. D-21014/8/2020-GAR dated 10/06/2024 on the subject cited above. In this connection it is to inform you that aforesaid premises/building is not in possession of valid fire safety certificate/NOC.

However, the said building was inspected by the officer concerned of this department on 26/02/2024 and noticed some deficiences, which were communicated to Mr. Amit Tayal(Addl. Director General) vide letter No F.6/DFS/MS/2024/SZ/78 dated 26/02/2024 (copy enclosed).

Yours faithfully

Encl.: As above

(Dr. S.K. Tomar) Dy. Chief Fire Officer Ph:-011-23412025

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6 /DFS/MS/2024/SZ/78

Dated: 26/02/2024

То

Mr. Amit Tayal (Addl. Director General) B Wing Hudco Vishala, Bhawan, 14, Bhikaji Cama Place, New Delhi-110066

Sub:

Reg. fire Safety certificate for renovation work at O/o DG-CCI Bhikaji Cama Place, New Delhi 110066

Sir.

This is in reference to your letter No. DG/CCI/IW/15/02/2022/98 Dated 08-02-2024 on the subject cited above. In this connection, it is to inform you that aforesaid premises have been visited by officer concern of this department on 16/02/2024 in the presence of Mohd Zakir Ali Asst. DG (CS) to verify the availability and operability of fire prevention and fire safety measures provided therein.

During the course of inspection, it was observed that the building is occupied by different govt. department. The shortcomings observed are as under;

1. Fire Check door found removed at some places in lift lobbies.

2. Smoke management system found not working.

3. First aid hose reel provided but found not working.

4. Automatic detector system found removed at some places.

5. Sprinkler system provides but found not working.

6. Fire fighting pumps are not on auto mode.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

(a) TOL GARG)

DELHI FIRE SERVICE

Copy to: -

 The Executive Engineer (Bldg.), MCD, Aurobindo Marg, Green Park, New Delhi 110016