

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/NDZ/2025/GH/ 3 80

Dated:

0001 ex voic rouse if at

To.

Mr. Sanjeev Malhotra, House No.J-8/71, 2<sup>nd</sup> floor, Tagore Garden, Rajouri Garden, Delhi-110027.

Sub: Renewal of FSC in r/o M/s Relax International located at 8225/1, Gali No.6, Arakashan Road, Multani Dhanda, Pahar Ganj, Delhi-110055.

Sir.

This is in reference to your online application No. 2025080112154 dated 05.08.2025 received in this department on the subject cited above. In this connection it is to inform you that the building was visited by officer of this department in presence of Mr. Md. Karim (Manager) on dated 25.08.2025 & it has been observed that the shortcoming already issued by this department letter of even No. 251 dated 23.05.2025 is not yet rectified (Copy enclosed). Therefore applicant is advised apply through the said online portal for further consideration in the matter after rectifying all the shortcomings.

Yours Faithfully

Encl; as above

(Virendra Singh) Chief Fire Officer **Delhi Fire Service** 

Copy to:-

MCD Portal ID-2025080112154 dated 05.08.2025.



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII WEADQUARTERS: DELIH FIRE SERVICE: NEW DELIH- 110001

No. F6/DFS/MS/GH/NDZ/2025/ 2:51

Dated: 23

To

The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi.

elt.medonline application no. 2025050207759 Ref:

Regarding renewal of Fire Safety Certificate in respect of M/s Relax International Sub: Guest House located at 8225/6, Arakashan Road, Pahar Ganj, New Delhi.

Sir,

With reference to the elt.mcdonline application no. 2025050207759 on the subject cited above, it is informed that the said guest house was inspected by the officer concerned of this department on, 17.05.2025 in the presence of Mr. Karim (Manager) and following shortcoming were observed at the time of inspection.

- 1. Hose reel found non functional.
- 2. CO detector found non functional.
- 3. Fire pump found non functional.
- 4. Overhead tank capacity of 2,500 litres has not been provided.
- 5. Public Address System found non functional.
- 6. Exit signages found removed.

In view of above shortcomings, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit

Your