

C-110

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No. F6/DFS/MS/NDZ/2025/ 792

Dated 15/05/2025

To,

The Inspector In-Charge,
RPF Post, Baroda House,
New Delhi.

Sub: - Regarding fixing of date for audit of Fire Fighting equipment in RPF Post Baroda house New Delhi.

Sir,

This has reference to your letter no. RPF/E-30/IOW/Baroda House/2025 dated 11.04.2025, & 08.05.2025, on the subject cited above. In this regard, it is to inform you that the matter was examined and observed that this department has already issued shortcomings vide letter no. F6/DFS/MS/2021/818 dated 09.04.2021 (copy enclosed).

Therefore, you are requested to submit the point wise compliance of shortcomings as issued vide above referred letter for further consideration in the matter. Moreover, it is also apprised that expected date and time for conducting the fire safety awareness/mock drill may please be conveyed to this department as per your convenience.

Encl. As above.

Yours faithfully,

(Atul Garg)
DIRECTOR
Delhi Fire Service

13/5/25

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F.6/DFS/MS/2021/ 818

Dated:- 9.4.2021

To,

Sr. Section Engineer (Works),
Northern Railways, Baroda House,
Headquarters Northern Railways,
Copernicus Marg, New Delhi.

Sub:- Regarding renewal of FSC in r/o Baroda House, Northern Railways Headquarters at
Copernicus Marg, New Delhi.

Sir,

This has reference to your e mail narenderkr.singhal@gmail.com Dated 09.03.21 on the subject cited above. In this regard, it is to inform you that the site (Block A & B (Annexe_I&II) was inspected by the officers concerned of this department on 24/03/2021 in the presence of Sh. Narendra Kumar (SSE) and the following shortcomings were observed:-

1. Alternate staircase at block -B (Annexe -II) found blocked/locked.
2. Fire check doors found broken at some places.
3. Corridors found encroached at some places.
4. Compartmentation is required in basement by erecting a wall to restrict of the smoke to upper floors.
5. Electrical shafts are not sealed horizontally /vertically.
6. Hose reel found nonfunctional.
7. Detectors found nonfunctional.
8. Sprinklers are required to be extended in left out areas of corridors.
9. MOEFA found nonfunctional.
10. PA system found nonfunctional.
11. Overhead water tank of 20000 ltr. is not provided at block -A (Annexe-1).
12. Pressurization in lift shaft not provided.
13. Exit/lift signages are not provided.

In view of above shortcomings, the application for issuance of Fire safety certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The licensing /statutory authority may take suitable necessary action as deemed fit .

Yours faithfully

(Atul Garg)

DIRECTOR

Delhi Fire Service

Copy to:-

1. The Chief Architect , NDMC , Palika Kendra , New Delhi.
2. Divisional Engineer, (Estate-I), Northern Railways, DRM Office,
New Delhi.