

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/CGHS/2025/NDZ/608

Dated: 17/04/2025

To,

Mr. Santosh Kumar (President),

Shekhar Cooperative Group Housing Society Limited

A - Block, Shehkar Apartments, Mayur Vihar Phase - I,

Extension, Delhi - 110091.

Subject: - Inspection Report in r/o M/s Shekhar Cooperative Group Housing Society limited located at A – Block, Shehkar Apartments, Mayur Vihar Phase – I, Extension, Delhi - 110091.

Sir,

Please refer to your Outdoor Dairy No. 47 dated 01/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officers concerned of this department on dated 09/04/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/NDZ2019/CGHS/1122 dated 20/05/2022 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: as above

(ATUI GARG)
DIRECTOR

DELM FIRE SERVICE

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/NDZ/2022/ CGns/ 1/22

Dated: 20 .05.2022

To

Sh. Devendra Kumar Rustagi, President, Life Manintenance Committee, Shekhar Apartment, Block- A, Mayur Vihar, Phase-I, Delhi – 91.

Subject:- Regarding issuance of Fire Safety Cert ificate in r/o Shekhar Apartment, Block-A, Mayur Vihar, Phase-I, Delhi - 91.

Sir,

This has reference to your email dated 28/12/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 25/04/2022 in the presence of Mr. K.K. Gaur (Executive Member) and the following shortcomings were observed:-

- 1. 06 mtr. access encroached one side due to planters.
- Hose reel not functional.
- 3. Two ground pumps having capacity of 2400 LPM are not provided.
- 4. Terrace pump having capacity of 900 LPM not provided.
- 5. MCP not functional.
- 6. Exit signage & lift signage not provided.

Hence, Fire Safety Certificate can not be consider at this stage. Your are advised to apply for issuance of Fire Safety Certificate after rectification of above mentioned shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully,

Delhi Fire Service

K