



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/CGHS/2025/NDZ/ 1323

Dated: 01/08/2025

To,

Mr. Keshav Kumar Gaur,
Shekhar Cooperative Group Housing Society Limited
A – Block, Shekhar Apartments, Mayur Vihar Phase – I,
Extension, Delhi - 110091.

Subject: - Inspection Report in r/o M/s Shekhar Cooperative Group Housing Society limited located at A – Block, Shekhar Apartments, Mayur Vihar Phase – I, Extension, Delhi - 110091.

Sir,

Please refer to your Outdoor Dairy No. 2769 dated 16/06/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officers concerned of this department on dated 12/07/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/NDZ2019/CGHS/1122 dated 20/05/2022 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,


30/7/2025

VIRENDRA SINGH
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

ok


Enclosed: as above

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F.6/DFS/MS/NDZ/2022/ CGMS/ 1122

Dated: 20.05.2022

To

Sh. Devendra Kumar Rustagi,
President,
Life Maintenance Committee,
Shekhar Apartment, Block-A,
Mayur Vihar, Phase-I, Delhi - 91.

Subject:- Regarding issuance of Fire Safety Certificate in r/o Shekhar Apartment, Block-A, Mayur Vihar, Phase-I, Delhi - 91.

Sir,

This has reference to your email dated 28/12/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 25/04/2022 in the presence of Mr. K.K. Gaur (Executive Member) and the following shortcomings were observed :-

1. 06 mtr. access encroached one side due to planters.
2. Hose reel not functional.
3. Two ground pumps having capacity of 2400 LPM are not provided.
4. Terrace pump having capacity of 900 LPM not provided.
5. MCP not functional.
6. Exit signage & lift signage not provided.

Hence, Fire Safety Certificate can not be consider at this stage. Your are advised to apply for issuance of Fire Safety Certificate after rectification of above mentioned shortcomings under intimation to this department for taking necessary action in this matter.

Yours faithfully,


(Atul Garg)
Director
Delhi Fire Service
