

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/NDZ/2024/ 1325

Dated: 24/06/2024

To

The President,
Shri Guru Jambheshwar Sansthan bhawan,
Civil Line, Behind I.P. College, New Vikas Bhawan II,
Upper Bela Road, Delhi - 54.

Sub: Regarding renewal of Fire Safety Certificate (FSC) in r/o **Shri Guru Jambheshwar Sansthan Bhawan, Civil Line, Behind I.P. College, New Vikas Bhawan II, Upper Bela Road, Delhi.**

Sir,

This has reference to letter outdoor diary no. 2438 dated 04.06.2024 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 19.06.2024 and observed that the shortcomings intimated vide letter of even No. F6/DFS/MS/NDZ/2023/4174 dated 07.11.2023 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Encl.: As above.

Yours faithfully,


(Atul Garg)

Director
Delhi Fire Service

Tel: 011-23414000

21/06/24
20/6

C-17

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

No.F6/DFS/MS/NDZ/2023/ 4174

Dated: 07/11/2023

To

The President,
Shri Guru Jambheshwar Sansthan Bhawan,
Civil Line, Behind I. P. College, New Vikas Bhawan II,
Upper Bela Road, Delhi - 54.

Sub:- Regarding issuance of Fire Safety Certificate in r/o Shri Guru Jambheshwar Sansthan Bhawan, Civil Line, Behind I. P. College, New Vikas Bhawan II, Upper Bela Road, Delhi.

Sir,

This has reference to letter outdoor diary no. 6843 dated 04.10.2023 received in this department, on the subject cited above. In this connection, this is to inform you that the school building was inspected by officer concerned from this department on 25.10.2023 in the presence of Sh. Mahavir (Manager). During the inspection, following shortcomings were observed:-

1. Hose reel found but not functional.
2. Fire pump not in auto start mode.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management.

Yours faithfully


(Atul Garg)
Director
Delhi Fire Service
Tel: 011-23414000

01/11

06/11