



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/Industrial/SZ/2025/ 410

Dated: 17/03/2025

To

The Authorized Signatory,
M/s SMS Export,
Plot No. D-28, Okhla Industrial Area, Phase- I,
New Delhi-110020.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s SMS Export located at Plot No. D-28, Okhla Industrial Area, Phase- I, New Delhi-110020.

Sir,

With reference to letter bearing outdoor diary no. 12397 dated 13.02.2025 on the subject cited above, it is informed that the said building was visited by officer concerned of this department on 10.03.2025 in the presence of Mr. Bhupender (HR Assistant)) and it was observed that the shortcomings issued to the building vide letter no. F6/DFS/MS/Industrial/SZ/2025/32 dated 20.01.2025 (Photocopy overleaf) has not been completely rectified till date. Hence renewal of Fire Safety Certificate cannot be considered at this stage.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Delhi Fire Service

Copy to:-

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

No. F6 /DFS/MS/Industrial/SZ/2025/ 39

Dated: 20 01

To.

The Owner/Occupier/Manager, SMS Export, Plot No. D-28, Okhla Industrial Area, Phase- I. New Delhi-110020.

Sub: - Regarding renewal of Fire Safety Certificate in r/o M/s SMS Export located at Plot No. D-28, Okhla Industrial Area, Phase- I, New Delhi-110020. Sir.

With reference to the letter bearing outdoor diary no. 11239 dated 09.01.2025 on the subject cited above, it is informed that the said building was inspected by officer concerned of this department on 16.01.2025 in the presence of Mr. Bhupender (HR Assistant) and following shortcomings were observed during the inspection.

- 1. Semi permanent & temporary construction on terrace floor shall be removed.
- 2. Standby pump found removed.
- 3. Fire pumps not in auto mode.
- 4. Terrace pump is not functional.
- 5. Overhead tank capacity 15,000 ltrs has been not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully.

Director

e Service

Copy to:-.

The Executive Engineer (Building), MCD, Jal Vihar, Lajpat Nagar, New Delhi-24