



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52025121700659

Dated: 26-02-2026

SHORTCOMING(S)

With reference to your application ID **52025121700659** dated **26-02-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Bhikaji Cama Bhawan** at **Bhikaji Cama Place, New Delhi** from fire safety point of view in presence of **Mr. Sudhakar Bharti** on dated **21/01/2026** During the course of inspection following observations were made:-

1. Fire check door not provided.
2. Smoke management not provided in basement.
3. Detectors provided but found non functional.
4. MOEFA, PA system, Pump, Sprinkler system in basement, Hydrant provided but found non functional.
5. Exit signage not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Dy.Chief Fire Officer

Copy to:-

1. Sudhakar Bharti , F 448 A/4, GALI NO 23 SADHNAGAR, SADHNAGAR, PALAM, 110045
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.