



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026021701086

Dated: 07-04-2026

SHORTCOMING(S)

With reference to your application ID **52026021701086** dated **07-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **DR. B.R. AMBEDKAR, C.B. SR. SEC SCHOOL** at **MEHRAM NAGAR, DELHI CANTT, NEW DELHI - 110010** from fire safety point of view in presence of **Smt. Bala Singhal, Principal** on dated **25/02/2026** During the course of inspection following observations were made:-

1. Fire Extinguisher found non functional.
2. Hose reel Hose found non functional.
3. Discharge and head of pump found non functional.
4. Overhead tank found empty.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Dy.Chief Fire Officer

Copy to:-

1. Chief Executive Officer , Delhi Cantonment Board, Sushma Swaraj Marg, Sadar Bazar, Delhi Cantt, Delhi, 110010
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.