



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026032001756

Dated: 24-04-2026

SHORTCOMING(S)

With reference to your application ID **52026032001756** dated **24-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Bal Vikas Convent School** at **478/5, Sai Nagar, Meethapur Extension, New Delhi - 110044**. from fire safety point of view in presence of **Mr, Vijay** on dated **16/04/2026** During the course of inspection following observations were made:-

01. First Aid Hose Reel provided but found nonfunctional.
02. Terrace Level Pump is of 220 LPM provided but found nonfunctional.
03. Overhead tank capacity 25,00 liters found removed.
04. Exit & floors Signage's not provided at strategic location in the building.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-

1. VIJAY BAHADUR SINGH , H NO 478 GALI NO 4, SAI NAGAR MEETHAPUR EXTN, BADARPUR , NEW DELHI, 110044
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.