



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026062904034

Dated: 10-09-2026

SHORTCOMING(S)

With reference to your application ID **52026062904034** dated **10-09-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Vikrant Tower** at **Plot No. 04, Rajendra Place, New Delhi-110008** from fire safety point of view in presence of **Rajesh Kumar** on dated **25/08/2026** During the course of inspection following observations were made:-

1. Emergency exit found blocked at many locations.
2. Exhaust fan found removed in basement.
3. Fire Extinguisher found empty at 13 floor.
4. Main electrical fire pump not working.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Dr.S.K.Tomar
Chief Fire Officer

Copy to:-

1. RAJESH KUMAR SONI , HOUSE NO 66, BLOCK D, GULMOHAR PARK, NEW DELHI, 110049
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.