



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



Application ID. 52026072804730

Dated: 10-09-2026

SHORTCOMING(S)

With reference to your application ID **52026072804730** dated **10-09-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Videocon Tower** at **Block-E1, Jhandewalan Extension, New Delhi** from fire safety point of view in presence of **Sh. Sanjeev Tiwari, Admin** on dated **11/08/2026** During the course of inspection following observations were made:-

1. Alternate staircase having width of 1.25m found removed in 2nd basement
2. The floor was found divided and locked into two separate entities, and the alternate access was also found locked.
3. The FCD glass provided in the staircase was found replaced with ordinary glass.
4. One FHC was found locked and inaccessible on the 12th floor.
5. The sprinkler valve on the 12th floor was found closed.
6. Staircase and lift pressurisation systems were found non-functional.
7. One lift was found removed.
8. The second floor was found locked and closed.
9. Ventilation opening windows at various floors were found jammed & removed/blocked.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Dr.S.K.Tomar
Chief Fire Officer

Copy to:-

1. SANJEEV TIWARI , 4/4, LABOUR COLONY, LAL QUARTER, GHAZIABAD, GHAZIABAD, 201001
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.