



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/School/2026/612

Dated: - 02/07/2026

To,

The Principal,
Venkateshwar Global School,
Sector-13, Rohini, Delhi-110085.

Sub.: - Regarding renewal of Fire safety Certificate in r/o Venkateshwar Global School, located at Sector-13, Rohini, Delhi-110085.

Sir,

This has reference to DFS online portal application no. 52025121200498 on the subject cited above, it is to inform you that the said building premises was re-inspected by the officer concerned of this department on 13/06/2026 in the presence of Sh. Rajnish Kumar (Manager) to check the compliance of shortcomings issued by this department vide application ID No. 52025121200498 dated 16/01/2026 (copy enclosed).

During inspection, it has been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above, the application for renewal of Fire Safety Certificate cannot be considered at this stage & **rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

Encl: as above

(S.K. Dua)
Chief Fire Officer
Delhi Fire Service

Copy to :-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi - 110054.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



Application ID. 52025121200498

Dated: 16-01-2026

SHORTCOMING(S)

With reference to your application ID 52025121200498 dated 16-01-2026 on the subject cited above, it is informed that officer concerned of this department inspected the Venkateshwar Global School at Sec-13, Rohini, Delhi-110085 from fire safety point of view in presence of Sh. Rajnish Kumar (Manager) on dated 02/01/2026 During the course of inspection following observations were made:-

1. Parking Area of School in basement found converted into auditorium hall & other student activity.
2. Fire check door found removed from staircases.
3. Changes in building are observed w.r.t. approved building plans by this department as two staircases are not going up to terrace.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Dy.Chief Fire Officer

Copy to:-

1. RAJNISH KUMAR , H-1,/34, BLOCKH-1, SHARMA COLONY, BUDH VIHAR, PHASE-2, NEW DELHI, 110085
2. The Concerned Local/Statutory Authority -

This letter is computer generated and does not require signature.