



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/GH/2025/SZ/ 276

Dated: 06/06/2025

To

The Joint Commissioner of Police (Lic.),
First Floor, P.S. Defence Colony,
New Delhi-110049


Sub: Inspection report in r/o M/s Abhishek Residency at TA 126, 2nd Floor, Tughlakabad, Okhla Main Road, New Delhi-110019

Sir,

Please refer to the online portal (etl.mcdonline.nic.in) ID. No. **2025051508500** dated 16/05/2025. In this connection, it is to inform you that the said premises was re-visited by the officer concerned of this department on dated 29/05/2025 in the presence of Mr. Jitender (House Keeping) to verify the compliance of shortcomings issued vide letter No. F.6/DFS/MS/GH/2025/SZ/248 dated 21/05/2025 and observed that the shortcomings are not yet complied.

In view of above, application for issuance of Fire Safety Certificate is rejected. The occupancy of the premises in the absence of requisite fire safety arrangements/certificate shall be at the risk and liability of the owner/occupier.

Yours faithfully,


31/6/2025
(Virendra Singh)
Chief Fire Officer
Delhi Fire Service
01/06/25

Copy to: -

1. Sh. Mohan Ahuja M/s Abhishek Residency at TA 126, 2nd Floor, Tughlakabad, Okhla Main Road, New Delhi-110019

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001**

No. F.6/DFS/MS/GH/2025/SZ/241
To

Dated: 21/05/2025

The Joint Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony,
New Delhi 110049

Sub: Regarding renewal of FSC in r/o M/s Abhishek Residency, TA-126, 2nd floor,
Tughlakabad Exnt., Okhla Road, New Delhi-19

Sir,

This is in reference with **MCD Portal ID 2025042106846 dated 21/04/2025** on the subject cited above. In this connection, it is inform you that the premises have been inspected by officer concerned of this department on 19/05/2025 in the presence of Mr. Jatin Kumar (Manager) of the Guest House. During the inspection, it was observed that the guest house is running at 2nd floor only. The shortcomings observed are as below;

1. Overhead tank capacity 9,000 ltrs provided against the required capacity of 10,000 ltrs.
2. Exit Signage found removed at some places.
3. Party hall running at 3rd floor & 4th Floor (Part Portion) in the building not allowed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE