

4
d/296

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/NDZ/2025/ 92

Dated: 05/03/2025

To,

The Chief Manager,
17, First floor, Indian, Bank Building,
Sansad Marg, New Delhi.

Sub:- : Issuance of FSC (Fire Safety Certificate) in r/o Allahabad Bank Building, 17, Parliament Street, New Delhi.

Sir,

This has reference to your letter on. FGMO/EXP/AK/Fire-Safety/2024-25 dated 21.01.2025, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 21/02/2025 in the presence of Mr. Ashok, Chief Manager and following shortcomings were observed: -

1. Hydrant & hose reel are not covering entire area and also not extended in one part of basement as basement is segregated through partition wall.
2. Sprinklers not provided in entire basement.
3. Alternative staircase exit in basement found locked/blocked.
4. Electrical shafts/ openings are not sealed properly.
5. Detectors are not provided some offices.
6. Fire Check Door not provided in basement.
7. Third floor & 4th floor are under renovation and firefighting system is dismantled at these floors.
8. Oiled filled transformer, provided at basement is required to be replaced with dry type transformer.
9. Pruning of trees is required for freely access of fire tenders.

In view of above, FSC cannot be issued at this stage. Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

(Atul Garg)

DIRECTOR

Delhi Fire Service

Copy to:-

The Chief Architect, NDMC, Palika Kendra, New Delhi.