

c/300

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/NDZ/2025/ 342

Dated: 15/07/2025

To,

The Chief Manager,
17, First floor, Indian, Bank Building,
Sansad Marg, New Delhi.

Sub:- : Issuance of FSC (Fire Safety Certificate) in r/o Allahabad Bank Building, 17, Parliament Street, New Delhi.

Sir,

This has reference to your letter on. FGMO/EXP/AK/Fire-Safety/2025-26 dated 09.06.2025, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 03/07/2025 in the presence of Mr. Ashok, and following shortcomings were observed: -

1. Hose reel is not provided at upper floor & Hydrant is not provided in basement.
2. Fire check doors is not provided in basement.
3. Oiled filled transformer, provided at basement is required to be replaced with dry type transfer.
4. Pruning of trees is required for freely access of fire tender.

In view of above, FSC cannot be issued at this stage. Therefore, you are requested to rectify the above shortcomings at the earliest under intimation to this department. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully

(Anil Garg)
DIRECTOR

Delhi Fire Service

Copy to:-

The Chief Architect, NDMC, Palika Kendra, New Delhi.