

No. F.6/DFS/MS/EH/2025/SZ/ 167

Dated: 01 05 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Amaltas Indian Tapas at M-25, First Floor, Greater Kailash-2, New Delhi- 110048, running at first floor only in a building comprised of basement (other property), ground plus three upper floors, owned/occupied by A unit of Arigo Ventures Pvt. Ltd., was issued FSC by this department vide Letter No. F.6/DFS/MS/EH/2022/SZ/290 dated 18.10.2022. The Restaurant building was re-inspected by the officer concerned of this department on dated 28.04.2025 in the presence of Mr. Udit Maheshwari, and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (First floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. of 2010 25 and valid up-to 31.03.2028, accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 01 05 2025 at New Delhi.

Delhi Fire Service

Online application Id 2025040305420 dated 04.04.2025

<u>Copy to</u>: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi. :-for information regarding use of basement.

Conditions for validity of Fire Safety Certificate: -

- 1. This NOC is valid only for First floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. Basement strictly shall be kept vacant as seen during inspection/used as per BBL.
- 8. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building:

M/s Amaltas Indian Tapas (Unit of Arigo Ventures Pvt. Ltd.) at

M-25, Greater Kailash-2, New Delhi- 110048.

2. Building is comprised of

Basement, ground plus three upper floors

3. Type of Occupancy

Group D (Assembly) Restaurant running at first floor only

4. Type of Case

Renewal

5. Details of Previous NOC

F.6/DFS/MS/EH/2022/SZ/290 dated 18.10.2022

6. Fire Safety directives letter No :

N/A

7. Date of inspection

28.04.2025

8. Name of Inspecting Officers

A.D.O. R.K. Yadav (JKP)

9. Name and designation of officers

From the building side

Mr. Udit Maheshwari

10. Year of Construction

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements As per Old FSC	Provided at site	Remarks MR/NMR				
1.	Access to building							
	Road width	06 m	Provided	M/R				
	Gate width	N/A	N/A	N/A				
	Width of internal road	N/A	N/A	N/A				
2.	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	Upper Floors	02 no's	02 no's	MR				
	Basements	N/A	Other Property	N/A				
	b. Width of staircases		Other Property	IN/A				
	Upper Floor	Required	1.30 & 0.93 m	MR, old case				
	Basements	N/A	N/A	N/A				
	c. Protection of exits		IVA	IN/A				
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of continuous staircases to		N/A	IVA				
	terrace	01 No's	Provided	MR				
	e. Width of Corridor	N/A	N/A	N/A				
	f. Door Size	Required	1.10 & 0.86 m	MR, old case				
3.	Compartmentation			Tritt, old cast				
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	Fire Rating of shaft door	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
4.	Smoke Management System							
	Basements	N/A	N/A	N/A				
	Upper floors	12 ACPH	Exhaust Fan Provided	MR				
5.	Fire Extinguishers							
	Total numbers in restaurant	08 no.'s	Provided	M/R				
	Types	ABC/CO ₂	ABC- 04 & Co2- 04	M/R				
	IS marking	ISI marked	Provided	M/R				
j.	First-Aid Hose Reels							
	Total numbers at each floor	. 1 Nos.	Provided	M/R				
	 Length of hose reel hose 	30 mtrs	Provided	M/R				
	Nozzle diameter	5 mm	Provided	M/R				

7.	Automatic fire detection and alarming system in restaurant						
	Type of detectors Smoke/Heat	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	 Location of Repeater Panel 	N/A	N/A	N/A			
	Alternate source of power Hooters' Location	N/A	N/A	N/A			
		N/A	N/A	N/A			
8.	MOEFA	Required	Provided	M/R			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	Basement	Required	Provided	MR			
	 Upper floors/Restaurant 	Required	Provided	MR			
	Sprinkler above false ceiling	N/A	N/A	N/A			
l 1.	Internal Hydrants						
	Size of riser/down-comer	N/A	100 MM	N/A			
	Number of hydrants	N/A	01 no's	N/A			
	Hose Box	N/A	01 no's	N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A N/A	N/A N/A			
3.	Pumping Arrangements		N/A	IVA			
	Ground Level						
	> Discharge of main Pump	21/4		4			
	➤ Head of Main pump	N/A N/A	N/A	N/A			
	> Number of main pumps	N/A N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	> Standby Pump out put	N/A	N/A N/A	N/A			
	 ➤ Standby Pump Head ➤ Auto Starting/Manual Stopping ➤ Pump House Access 	N/A	N/A N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A N/A			
	_		- 1/2-2	IVA			
	Terrace level	450 & 180 LPM	450 & 180 LPM	M/R			
	 Discharge of pump Head of the pump Power Supply Auto Starting of pump 	40 m	Provided	M/R			
		Required	Provided	M/R			
		Required	Provided				
4.			Frovided	M/R			
•••	Captive Water Storage for fire-fighting						
	> Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	N/A	N/A	N/A			
		5,000 ltrs	Provided	M/R, old car			
5.	Exit Signage.	Required	Provided	M/R			
5.	Provision of Lifts	1 10 1		- (
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	Required	Provided	M/R			
	Fireman's Grounding Switch	Required	Provided	M/R			
	Lift Signage	Required	Provided	M/R			
•							

MB

1	Standby power supply	Required	Provided	M/R		
	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
9.	Fire Control Room	N/A	N/A	Т		
	Detector System Panel Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel Battery backup	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
į	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/EH/2022/SZ/290 dated 18.10.2022, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Name- R.K. Yadav

Designation- ADO (JKP)

DO (SD)

Ċ

4/1 1 1

30 Tul (300)

m

6115128

D