GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELH HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

र्गापादी स अमृत महोत्सव

No. F6/DFS/MS/SCHOOL/NDZ/2025/ 444

Dated: 23/05/2025

To,

The Principal,
Amar Jeevan Public School,
F-190, Laxmi Nagar,
Near Mangal Bazar,
Delhi – 110092.

Subject: - Regarding Grant of Fire Safety Certificate in r/o Amar Jeevan Public School located at F-190, Laxmi Nagar, Near Mangal Bazar, Delhi – 110092.

Sir,

Please refer to your letter outdoor diary No. 1505 dated 08/05/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on 16/05/2025 in the presence of Principal and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2025/177 dated 26/03/2025 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

CDELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, MCD, Civic Centre, Jawahar Lal Nehru Marg, New Delhi - 110002.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/School/NDZ/2025/177

Dated: 36 /03/2025

To,

The Principal, Amar Jeevan Public School F-190, Laxmi Nagar, Delhi - 110092.

Subject: - Regarding grant of Fire Safety Certificate in r/o Amar Jeevan Public School located at F - 190, Laxmi Nagar, Delhi - 110092.

Sir.

This has a reference to your Outdoor diary No. 13040 dated 28/02/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 18/03/2025 in the presence of Mr. Sanjay Kumar (Principal) and observed that building comprised of ground plus three upper floors.

Following shortcomings were observed during time of inspection:

- 1. Second staircase found removed. One fire escape of width 0.75 m is required to be provided from Ground to upper floors.
- 2. First-Aid-Hose Reel found removed.
- Fire pump of 220 LPM found removed.
- 4. Over head water storage tank of capacity 5,000 liters found removed.
- 5. Exit & floors Signage's found removed at strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit. Yours faithfull

The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.