



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/2025/SZ/ 150

Dated: 07/04/2025

To

The Joint Commissioner of Police (Lic.),
1st Floor, P.S. Defense Colony
New Delhi-110049

Sub: Inspection report in r/o M/s Ankara (ONS Hospitality) located at Shop/Prop. No. 3, EFGH Block, Masjid Moth, New Delhi-110048

Sir,

Please refer to the online portal (etl.mcdonline.nic.in) Id. No. 2025031503579 dated 24/03/2025. In this connection, it is to inform you that the said premises was visited by the officer concerned of this department on dated 01/04/2025 in the presence of Sh. Ajay Mishra (Manager) of the eating house to verify the compliance of shortcomings issued by this office vide letter No. F.6/DFS/MS/EH/2024/SZ/520 dated 27/11/2024 and observed that the shortcomings are not complied as yet.

In view of above, application for issuance of Fire Safety Certificate is rejected. The occupancy of the premises in the absence of requisite fire safety arrangements/certificate shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(ATUL GARG)
DIRECTOR

Ph 011-23414000

Copy to: -

1. Sh. Pradeep Vig, M/s Ankara (ONS Hospitality) located at Shop/Prop. No. 3, EFGH Block, Masjid Moth, New Delhi-110048

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/EH/2024/SZ/ 520
To

Dated: 27.11.2024

The Addl. Commissioner of Police (Lic/Unit),
1st Floor, P.S. Defence Colony,
New Delhi-110049.

Sub: Regarding issuance of FSC in r/o **M/s Ankara** located at First Floor, Property
No 3, LSC Market, Masjid Moth, G.K New Delhi -110048

Sir,

This is in reference with **MHR Portal ID 2024042406037 dated 11/11/2024** on the subject cited above. In this connection, it is to inform you that the premise have been inspected by officer concerned of this department on 22/11/2024 in the presence of Mr. Sanjay (Manager) and to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

1. First aid hose reel provided but found not working.
2. Internal hydrant provided but found not working.
3. Fire fighting pumps are provided but found not working.
4. Exit signage's found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE