



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/2025/NDZ/260

Dated 22/04/2025

To,

The Principal,
Anuradha Public School
A – 116, Sukkar Bazar, Ashok Nagar,
Mandoli Road, Delhi - 110093.

Sub.: - Inspection Report in r/o Anuradha Public School located at A – 116, Sukkar Bazar, Ashok Nagar, Mandoli Road, Delhi - 110093.

Sir,

Please refer to your Outdoor Dairy No. 12531 dated 17/02/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 05/04/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2019/NDZ/1302 dated 15/03/2019 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: as above

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Director of Education, MCD, Udyog Sadan Plot bNo. 419, FOE, Patparganj, Delhi - 110092.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/School/2019/NDZ/ 1302

Dated: 15/03/19

To,

The Headmistress,
M/s Anuradha Public School
A-116, Sukkar Bazar chowk, Ashok Nagar,
Delhi-110093

Sub:- Regarding Issuance of Fire Safety Certificate in r/o M/s Anuradha Public School at A-116, Sukkar Bazar Chowk, Ashok Nagar, Delhi-110093.


Sir,

This is in reference to your letter No. APS/12/18, Dated- 27/12/18 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mrs. Renu Sharma, Headmistress of the School. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

1. One staircase of width 1.50 meter required.
2. Only 02 nos. fire extinguishers found provided in place of 06 nos. fire extinguishers as required
3. First-Aid hose reels (01 nos.) at each floor not provided.
4. A fire pump having 450 LPM output at 40 meters head not provided.
5. Over Head water storage tank 10,000 liters capacity exclusively for fire fighting not provided at terrace.
6. Exit signage not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully



(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy:-

The Director of Education, EDMC,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area,
Delhi-110092

de
OK