

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/2025/SZ/143

Dated: 25/03/2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s Araya Bagh (A unit of Kapco Banquets and catering Pvt Ltd) located at KH No. 43, 46, 47, 48, Village Sultanpur, M. G. Road, Adjoining Ghitorni Metro Station, New Delhi-110030 comprised of Basement, Ground and 1stfloor (BF-storage, GF-Halls, restaurants & office, 1st Floor- 04 Guest rooms) owned/occupied by A unit of Kapco Banquets and catering Pvt Ltd was issued FSC by this department vide letter No. F6/DFS/MS/Motel/SZ/2021/642 dated 30/12/2021 in name of Nandi Greens. The premise was re-inspected by the officer concerned of this department on 19/03/2025 in the presence of Mr. Prem and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy class A "Residential"(Motel) Building with effect 21/03/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on 25 03 not at New Delhi by.

(ATVL GARG)
| DIRECTOR
| DELHI FIRE SERVICE

Copy to:-

1. The Joint. C.P. (Lic), 1st Floor P. S. Defence Colony, New Delhi-110049.

 M/s Araya Bagh (A unit of Kapco Banquets and catering Pvt Ltd, KH No. 43, 46, 47, 48, Village Sultanpur, M. G. Road, Adjoining Ghitorni Metro Station, New Delhi.

## Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.

4. The basement shall be used as per the provisions of BBL-/NBC Part- IV.

- 5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms">http://delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms</a>
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



INSPECTION REPORT

1. Name & address of the building :The Araya Bagh at KH No. 43, 46, 47, 48, Village Sultanpur,

M.G. Road, Adjoining Ghitorni Metro Station, New Delhi

: Group A "Residential" (Motel) 2. Type of Occupancy : Basement + GF + 1st Floor 3. Comprised of

4. Type of Case : Renewal

: F6/DFS/MS/Motel/SZ/2021/642 dated 30/12/2021 5. Details of Previous NOC 6. Fire Safety directives letter No : F6/MS/DFS/BP/2006/488 Dated 27/02/2006

7. Date of inspection : 19/03/2025

8. Name of Inspecting Officer : Sh. Rajesh Kumar ADO (BCP)

9. Name and designation of officers

From the building side : Mr. Prem 10. Year of Construction : 2009

S. No	Minimum Standards on fire prevention and fire safety U/R 33	Old NOC (26-11-2010) Requirement	Provided at site	Remarks MR/NMR		
1.	Access to building	Amada area				
	<ul> <li>Road width</li> <li>Gate width</li> <li>Width of internal road</li> </ul>	Approachable Adequate -NA-	30m 5m 6m	MR MR -NA-		
2.	Number, Width, Type & Arrangement of	Exits				
	a. Number of staircases					
	Upper Floors	Three	Provided	MR		
	Basements	Four	Provided	MR		
	b. Width of staircases	THE PERSON NAMED IN	C S TARE N			
	Upper Floor	1.5m	1.5m	MR		
	Basements     Protection of exits	3 x 1.5m + one of 1.2-1.5m	3 x 1.5m + one of 1.2-1.5m	MR		
	Fire check door	Required	Provided	MR		
	Pressurization	-NA-	-NA-	-NA-		
	d. No. of continuous staircases to terrace	Three	Three	MR		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	NA	1m (Final Exit)	NA		
3.	Compartmentation   Compartmentat					
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	-NA-	-NA-	-NA-		
	Water Curtain	-NA-	-NA-	-NA-		
	Fire Dampers	-NA-	-NA-	-NA-		
1.	Smoke Management System					
•	Basements	30 ACPH	M.V.S.	MR		
		12 ACPH	Natural ventilation	-NA-		
	Upper floors	12 ACFII	Natural ventilation	-NA-		
5.	Fire Extinguishers	Dortable Fire	20 Maia	MR		
	Total numbers	Portable Fire Extinguishers	20 No's ABC/W.Co <sub>2</sub> /Co <sub>2</sub> .	MR		
	<ul><li>Types</li><li>IS marking</li></ul>	ISI Marked	10/10/-	NIX.		
	• 13 marking	101 Willikou	Yes	MR		
6.	First-Aid Hose Reels					
	<ul> <li>Total numbers on each floor</li> </ul>	Hose Reels	2 No's	MR		
	<ul> <li>Length of hose reel hose</li> </ul>		30m	MR		
	Nozzle diameter		5mm	MR		
7	Automatic fire detection and alarming system					
	Type of detectors	Required	Smoke & Heat	MR		
	Location of Main Panel	-NA-	Ground Floor	-NA-		
	Location of Repeater Panel  M/s Araya Bagh (A unit of Kapco Banquets and	-NA-	-NA-	-NA-		

		N130			
	Alternate source of power	Required	Provided	Mix	
	Hooters' Location	Required	All Floors	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System	Required		1	
	Basement	Required	Provided	MR	
	Ground Floor	Required	Provided	MR	
	Sprinkler above false ceiling	Required	Provided	MR	
11.	Internal Hydrants	Required		197	
	Size of riser/down-comer	Required	100mm	MR	
	Number of hydrants per floor	Required	2 Nos	MR	
	Hose Box	Required	2 Nos	MR	
12.	Yard Hydrants				
T	Total number of hydrants	Required	4 No's provided	MR	
	Hose Box	Required	4 No's provided	MR	
13.	Pumping Arrangements	Acquired	Hall drugger and	100	
	Ground Level	I			
	<ul> <li>Discharge of main Pump</li> </ul>	Required	1620 LPM	MR	
	➤ Head of Main pump	Required	56m	MR	
	Number of main pumps	Required	One	MR	
	<ul> <li>Jockey Pump out put</li> </ul>	Required	180 LPM	MR	
	> Jockey pump head	Required	56m	MR	
	Standby Pump out put	Required	1620 LPM	MR	
	Standby Pump Head	Required	56m	-NA-	
	➤ Auto Starting/Manual Stopping	Required	Provided	MR	
	- 11 -	Required	Provided		
	> Pump House Access	Required	Flovided	MR	
	Terrace level     Discharge of nump	Dogwised	000 1 D) (	1.00	
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	Required Required	900 LPM 36m	MR	
	Power Supply	Required	Provided	MR MR	
	> Auto Starting of pump	Required	Provided	MR	
	T NAT	ti i lam Unic I	lan marking a	IVIIC	
14.	Captive Water Storage for fire fighting				
	<ul> <li>Underground tank capacity</li> </ul>	1,00,000 Lts	1,00,000 Lts	MR	
	Draw-off connection	Required	Provided	MR	
	Fire service inlet	Required	Provided	MR	
	Access to tank	Required	Provided	MR	
	Overhead Tank capacity	10,000 Lts	10,000 Lts	MR	
15.	- Commercial Control C	Required	Provided	MR	
16.	Provision of Lifts.	100000			
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-	
	Pressurization of Lift lobby     Communication In Lift Com	-NA-	-NA-	-NA-	
	Communication In lift Car     Firemen's Grounding Switch	-NA-	-NA-	-NA-	
	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>	-NA-	Provided	-NA-	
	Lift Signage	-NA-	-NA-	-NA-	
17.	Standby power supply	Required	Provided	MR	
18.					
	> Total Area	-NA-	-NA-	-NA-	
	> Location	-NA-	-NA-	-NA-	
19.	Fire Control Room	11.	,,,,		
	Detector System Panel	-NA-	-NA-	-NA-	
	Flow Switch Panel	-NA-	-NA-	-NA-	
	PA System Panel	-NA-	-NA-	-NA-	
	Battery backup	-NA-	-NA-	-NA-	
	Dattery Dackup				

M/s Araya Bagh (A unit of Kapco Banquets and catering Pvt Ltd), KH No. 43, 46, 47, 48, Village Sultanpur, M.



## 20. Special Fire Protection System for Protection of special Risks, if any:

-NA-

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Motel/SZ/2021/642 dated 30/12/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (SD)

Directory

12)

As approved, F.T. Letter

i p

portup for

24/3/2025

your

Sinector M

 $\sim$