



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/School/2025/SZ/183

Dated: 23/10/2025

To,

The Principal,
M/S Brainbells Public School,
H-16/1489, Near Shiv Mandir,
Sangam Vihar, New Delhi.

Subject: - Regarding issuance of Fire Safety Certificate in r/o M/S Brainbells Public School located at H-16/1489, Near Shiv Mandir, Sangam Vihar, New Delhi.

Sir,

Please refer to your outdoor dairy No. 6055 dated 16/09/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 06/10/2025 in the presence of Mr. Ashish Khawal (Principal) and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/SZ/2024/183 dated 23/04/2024 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclose as above


(A.K. Malik)

Dy. Chief Fire Officer
o/c Delhi Fire Service

Copy to: -

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/5
आग प्रशिक्षण
अभ्यास महेन्द्र

No.F6/DFS/MS/School/SZ/2024 | 183

Dated: 23/04/2024

To

The Principal,
M/s Brainbells Public School,
H-16/1489, Near Shiv Mandir,
Sangam Vihar, New Delhi.

Sub:- Regarding issuance of Fire Safety Certificate in r/o M/s Brainbells Public School located at H-16/1489, Near Shiv Mandir, Sangam Vihar, New Delhi.

Sir,

With reference to letter bearing outdoor diary no. 13949 dated 06.03.2024 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 05.04.2024 in the presence of Mr. Ashish Khawal (Principal) and it was observed that the building is comprised of Lower Ground + Ground + 1 upper floors. During the inspection following shortcomings were observed:-

1. 2 nos. of staircases 1.50 meters each not provided in the building.
2. Six nos. of Fire Extinguishers found not provided.
3. First aid hose reels found not provided.
4. Fire pump found not provided.
5. Terrace water tank of 10,000 liters found not provided (exclusively for firefighting).
6. Exit signages not provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Gang)
Director

Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.