

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



F6/DFS/MS/2025/SZ/ 106

Dated/3 /02 /2025

To.

The Joint Commissioner of Police/ Lic, 1st Floor, Licensing Unit, Police Station Defence Colony, New Delhi.

Sub: - Regarding issuance of fire safety certificate in r/o M/s Brandavan Food Products located at Plot No. F-90/11, First Floor, Okhla Industrial Area, Phase-I, Delhi-110020.

Sir,

This has reference to your letter received through online I.D No. 2025011300449 dated 20.02.2025 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 08.03.2025 in presence of Sh. Rahul (Manager) and verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no. F6/DFS/MS/2015/485 dated 11.03.2015 and observed that the shortcomings have not been removed so far.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department running/occupancy of the kitchen without Fire Safety Certificate is at the rise & responsibility of the management.

Yours faithfully

Ph. 011-23414000

Copy to :-

1. The Manager, M/s Brandavan Food Products located at Plot No. F-90/11, First Floor, Okhla Industrial Area, Phase-I, Delhi-110020.

رجاح

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI-HEAD QUARTERS: DELIH FIRE SERVICE: NEW DELHI-110001

E-mail: gargatula hotmail.com, Tel:- 011-26189168

No. F610F3/2512015 /415

Dated: 11/3 /15

To

Authorised Signatory,

- R.K. Associates & Hoteliers Pvt. Ltd.

F- 90/11, Okhla Phase-1,

New Delhi- 110020.

Sub.:- Inspection report in respect of R.K. Associates & Hoteliers Pvt. Ltd., F- 90/11, Okhla Phase-1, New Delhi from fire safety and means of escape point of view.

Sir.

Please refer to your letter No. Nil dated 17.12.2014 on the subject cited above. In this connection, this is to inform you that the inspection of the said premises has been carried out by the officers concerned of this department in presence Mr. Naveen Kumar, manager on 10-02-2015 to check the fire safety arrangements as per guidelines issued by this department vide letter No. F.6/DFS/MS/BP/2009/2126 dated 16.07.2009.

During inspection, it has been observed that the said building is comprised of basement, ground plus two upper floors served with two nos, of staircases having width 1.20 & 1.12 mts. Fire safety arrangements such as sprinkler system in basement, down comer, terrace pump, hose reel, detection system, MOEFA, different types of fire extinguishers, overhead water static tank capacity 5000 liters etc. found provided. However, the following shortcomings were observed:-

- 1. Width of staircase is less than required width.
- An additional overhead water tank capacity 15000 liters and an underground water tank capacity 75000 liter are required for fire fighting purposes.
- 3. Sprinkler system is not provided in ground and upper floors.
- Diesel & electric driven pumps capacity 2280 lpm each and one jockey pump capacity 180 lpm are not provided.
- MCP and detection system are provided but not functional.
- 6. Fire Check Doors are not provided in lift & staircase lobby at each floor.
- 7. Ventilation system is not provided in basement floor.
- Exit signs are not provided.
- 9. Fire extinguishers are provided but not adequate.

In view of the above shortcomings, fire safety certificate cannot be granted at this stage. You are requested to remove the above-mentioned shortcomings under intimation to this department.

Dy. CHIEF FIRE OFFICER

90

12/3/12-