0/10



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/2025/EH/ 3 12

Dated: 22/ 17/2025

To '

The Dy. Health Officer, Sector-5, Institutional Area, Rohini, Delhi-110085

Regarding issuance of fire safety certificate in r/o M/s Burger King (A Unit of Restaurant Brands Asia Ltd) at Unit No. 7, 8, 9, 10, 38, 39, 40 & 41, Ground floor, Sector-18, Block E, Rohini, Delhi-110089

Sir,

This has reference to online MCD Portal ID No. 2025062310431 dated 23/06/2025 on the subject cited above. In this connection, this is to inform you that the said premises was inspected by the officers concerned of this department on 14/07/2025 in the presence of Mr. Ashish (Area Manager) and the shortcomings observed are as below.

1. No Imaginary corridor has been left.

2. The exit door width 1.10 is provided against the requirement of 1.50m each.

3. Exit signage's not found provided in the restaurant.

Keeping in view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. Applicant may be requested to rectify the above-mentioned shortcomings under intimation to this department; till such time running of restaurant shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(Virendra Singh) Chief Fire Officer Delhi Fire Service