



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001</u>



No F6/DFS/MS/2025/EH/WZ/ 16/

FIRE SAFETY CERTIFICATE

Dated: 30/04/2025

Certified that the M/s Burger King India Ltd. located on Shop No. 3 to 10, Gr. floor, 16 Mangalam Palace, M2K, Sector-3, Rohini, Delhi-85, comprised of Basement + Ground + 02 upper floors but restaurant is running in a mall at Unit No. 3 to 10, gr. floor only, has already been issued FSC by this department vide letter No F.6/DFS/MS/EH/2022/Restaurant/WZ/79 dated 05.04.2022. The premises was re-inspected by the officer concerned of this department on 23.04.2025 in the presence of Mr. Imran (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group D "Assembly" (Eating House) for Unit No. 3 to 10, gr. floor only with effect from 3004 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30 04 2025 at New Delhi by

(Atul Garg) DIRECTOR Ph; 011-23414000

Copy to:-

1. MCD Portal ID. 2025040305512 dated 03.04.2025.

2. The Dy. Health Officer, North MCD, Sector-5, Rohini Zone Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

	-	A CAMP DE LA CAMP DE L						
			INSPEC	TION REPORT				
1. N	Name & ad	dress of the building	M/s Bu	rger King India Lt	d. loca	ted on Shop No. 3	to 10 Gr flor	
16 Ma				s Burger King India Ltd. located on Shop No. 3 to 10, Gr. floo Mangalam Palace, M2K, Sector-3, Rohini, Delhi-85				
2. 7	ype of Oc	cupancy	bly Building					
3. C	Comprised	of building	ent + Ground + 02 upper floors					
•	Rene Rene			Renewal (Restaurant is running in a mall at Unit No. 3 to 1				
5. I	Details of I	Pravious NOC	oor only)					
6 E' C C H				S/MS/EH/2022/Restaurant/WZ/79 dated 05.04.2022.				
7 D. All				JBC Part-IV 3.04.2025 /r. Suman Kumar (ADO)				
0 11 0								
-				mran (Manager)				
	From the	uilding side	Will. III	iran (ivianager)				
	Year of C		2003 0	n MCD Portal				
		s letter No.	75.5	application No.202	250403	05512 dated 03.04	2025	
.		Standards on fire prevent	tion and	BBL/NBC		ided at site	Remarks	
o	fire safety	U/R 33					MR/NMR	
۱.	Access t	building (Plot No.	16 Man	galam Palace M	Aall is	sued FSC vide	letter No	
	F.6/DFS/	MS/WZ/2023/85 dated 1	5.02.202	3)			MR	
	• Ro	ad width		Restaurant with	in 1	Provided by Mall		
	• Ga	te width		Plot No.16		-NA-	-NA-	
	• W	dth of internal road		Mangalam Palace Mall		-NA-	-NA-	
2.	Number,	Width, Type & Arrang	ement of	Exits	C	ommon with the r	nall	
	a. Number of staircases		e 111			1.75		
		Upper Floors		Restaurant within N		As Above	MR	
	s.	Basements		Restaurant within N	Mall	As Above	, MR	
	b. Width of staircases							
	•	Upper Floor		Restaurant within Mall		As Above	MR	
		Basements		Restaurant within Mall		As Above	MR	
	2	ction of exits					ı	
	. 1700	• Fire check door		Restaurant within Mall		As Above	MR	
		Pressurization		Restaurant within N	Mall	As Above	MR	
		No. of continuous staircases to terrace		Restaurant within Mall		As Above	MR	
	arman og dan		Restaurant within Mall		As Above	MR		
	f. Door Size		02 exits		2.09m & 1.55m	MR		
3.	Compartmentation							
J.	a) Fire check door			Restaurant within Mall		As Above	MR	
	b) Sealing of electrical shafts			Restaurant within Mall		As Above	MR	
		c) Fire Rating of shaft door		Restaurant within Mall		As Above	MR	
		Water Curtain		Restaurant within Mall		As Above	MR	
	-	Fire Dampers		Restaurant within Mall		As Above	MR	
4.	Smoke Management System							
-	a) Basements		Restaurant within Mall		As Above	MR		
	/) Upper floors		Restaurant within Mall		As Above	MR	
5.	Fire Extinguishers		common with the mall					
٥.	a) Total numbers			04nos.		Provided	MR	
		Гуреѕ		ABC/CO2		ABC/CO2	MR	
				ISI marked Yes		Yes	MR	
		S marking		1SI marked				
6.	c) I	marking Hose Reels		01 near to restau		As Above	MR	

· k

		N-0					
	b) Length of hose reel hose	30mm	As Above	MR			
	c) Nozzle diameter	5m	As Above	MR			
7.	Automatic fire detection and alarming sys	tem cor	nmon with the mall				
	a) Type of detectors	Restaurant within Mall	As Above	MR			
	b) Location of Main Panel	Restaurant within Mall	As Above	MR			
	c) Location of Repeater Panel	Restaurant within Mall	As Above	MR			
**	d) Alternate source of power	Restaurant within Mall	As Above	MR			
	e) Hooters' Location	Restaurant within Mall	As Above	MR			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Restaurant within Mall	As Above	MR			
10.	Automatic Sprinkler System	nmon with the mall					
	a) Basement	Restaurant within Mall	As Above	MR			
	b) Ground & Upper Floors	Restaurant within Mall	As Above	MR			
	c) Sprinkler above false ceiling	Restaurant within Mall	As Above	MR			
11.	Internal Hydrants common with the mall						
	a) Size of riser/down-comer	100mm	As Above	MR			
	b) Number of hydrants per floor	One(near to Restaurant)	As Above	MR			
	c) Hose Box	One(near to Restaurant)	As Above	MR			
12.	Yard Hydrants One(near to Restaurant) As Above MR						
	a) Total number of hydrants	Restaurant within mall	As Above	MR			
	b) Hose Box	Restaurant within mall	As Above	MR			
13.	Pumping Arrangements	The second secon	mon with the mall	IVIX			
	Ground Level	Con	imon with the man				
	➤ Discharge of main Pump	Restaurant within mall	As Above) (D			
	➤ Head of Main pump	Restaurant within mall	As Above	MR MR			
	 Number of main pumps 	Restaurant within mall	As Above	MR			
	> Jockey Pump out put	Restaurant within mall	As Above	MR			
	> Jockey pump head	Restaurant within mall	As Above	MR			
	Standby Pump out put	Restaurant within mall	As Above	MR			
	> Standby Pump Head	Restaurant within mall	As Above	MR			
		Restaurant within mall	As Above	MR			
		Restaurant within mall	As Above	MR			
	•			IVIIC			
	Terrace level common with the						
	➤ Discharge of pump	-NA-	As Above	MR			
	> Head of the pump	-NA-	As Above	MR			
is .	➤ Power Supply	Required	As Above	MR			
	➤ Auto Starting of pump	Required	As Above	MR			
14.	Captive Water Storage for firefighting common with the mall						
	Underground tank capacity	Restaurant within mall	As Above	MR			
	> Draw-off connection	Restaurant within mall	As Above	MR			
	> Fire service inlet	Restaurant within mall	As Above	MR			
	The Statement and Statement Statemen	Restaurant within mall	As Above	MR			
	> Access to tank		Castonian Caston				
	Overhead Tank capacity	Restaurant within mall	As Above	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						
	a) Pressurization of Lift Shaft	-NA-	As Above	-NA-			
	b) Pressurization of Lift lobby	-NA-	As Above	-NA-			
	o, a robbut Emilion of Entriolog			NIA			
	c) Communication In lift Car	-NA-	As Above	-NA-			

1/3							
19.	e) Lift Signage	-NA-	As Above	-NA-			
	e) Lift Signage Standby power supply	Required	As Above	-NA-			
	Defuge Area.			1171			
	a) Total Area	-NA-	As Above	-NA-			
	b) Location	-NA-	As Above	-NA-			
	Fire Control Room						
	a) Detector System Panel	Restaurant within Mall	As Above	MR			
	b) Flow Switch Panel	Restaurant within Mall	As Above	MR			
	c) PA System Panel	Restaurant within Mall	As Above	MR			
	d) Battery backup	Restaurant within Mall	As Above	MR			
	e) Building Floor Plans	Restaurant within Mall	As Above	MR			
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	Kitchen suppression system & gas detector found installed	-NA-			

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/EH/2022/Restaurant/WZ/79 dated 05.04.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

المالالم المعاملة

Signature of the Inspecting Officer
Name Suman Kumar
Designation ADO

DO (24W)

DO (24W)

Doled. 25 | 04 | 26 (W2)

Director My

Any Sh

F.T. pletter is but us for

pired my

Undander)

. CY 451 X