

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/2025/SZ/ 17)

Dated: 17.04.2025

To

Mr. Executive Engineer (CD-XV) DSIIDC,
Office of the Executive Engineer (CD-15(RP))
DSIIDC Building, Lajpat Nagar-III,
Ring Road, New Delhi.

Sub: Regarding issuance of FSC in r/o M/s Culture and Information Centre at DSIIDC's Facility Centre at Industrial Estate for Electronics at Okhla Ph-II, Pocket-A, New Delhi

Sir,

This has reference to with outdoor diary no 12423 dated 13/02/2025 on the subject cited above. In this connection, this is to inform you that inspection of the premise was conducted by the officer from Delhi Fire Service on 09.04.2025 in the presence of Mr. Mukesh Kumar (ED-II) DSIIDC to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. The pressurization system of lift lobbies, lifts well & staircase not provided.
2. Smoke management not working in basement and also fresh air duct shall also be provided.
3. First aid hose reel provided but found not working.
4. MOEFA not working.
5. Sprinkler system not working. The upright sprinkler needs to be provided above fall Ceiling.
6. Internal hydrant provided but found not working.
7. Fire fighting pumps provided but found not working.
8. Exit Signage not provided at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Dr / c