GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2025/SZ/ 298

Dated:

14/08/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Coffee Bean And Tea Leaf (A unit of Ekaagra Ostalariza Pvt. Ltd.) located at Property No. M-76, GF, M Block Market, Greater Kailash- II, New Delhi- 121004, running at ground floor only in a building comprised of basement (other property), ground plus three upper floors (1st, 2nd & 3rd floor used for office purpose), owned/occupied by A unit of Ekaagra Ostalariza Pvt. Ltd., have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010. and verified by the officer concerned of this department on dated 10.07.2025 in the presence of Ms. Deepa (Manager), and found that the building is fit for occupancy Class "D" "Assembly Building" (for ground floor only) w.e.f. 14 08 2025 valid up to 31.03.2028, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 14 08 2025 at New Delhi.

Chief Fire Officer Delhi Fire Service

Online application Id 2025062610604 dated 27.06.2025.

Copy to: - The Executive Engineer (Building), MCD, Civic Centre, Minto Road, New Delhi.

: - for information regarding use of basement and height verification.

Conditions for validity of Fire Safety Certificate:-

- 1. This FSC is valid only for ground floor.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. Basement shall be used as per BBL/UBBL.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 10. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT 1. Name & address of the building

M/s The Coffee Bean And Tea Leaf (A unit of Ekaagra Ostalariza Pvt. Ltd.) at Prop. No. M-76, GF, M-Block Market,

Greater Kailash- II, New Delhi- 121004.

2. Building is comprised of :

Basement (other property), Ground plus three upper floors Group D (Assembly) Restaurant running at Ground floor only

3. Type of Occupancy : Type of Case 5. Details of Previous NOC

New Case N/A

Fire Safety directives letter No

Nil

7. Date of inspection

10.07.2025 :

Name of Inspecting

A.D.O. R.K. Yadav (JKP)

9. Name and designation of officers

From the building side

Ms. Deepa (Manager) 2024

10. Year of Construction

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements	Provided at site	Remarks MR/NMR
1.	Access to building			
	Road width	06 m	Provided	M/R
	Gate width	N/A	N/A	N/A
	 Width of internal road 	N/A	N/A	N/A
2.	Number, Width, Type & Arrangeme		(Restaurant at Gr	
	a. Number of staircases			
	Upper Floors	N/A	27/4	
	Basements	N/A	N/A	N/A
	b. Width of staircases	N/A	N/A	N/A
	Upper Floor	N/A		
	Basements	N/A	N/A	N/A
	c. Protection of exits	IVA	N/A	N/A
	Fire check door	N/A	N/A	
	Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to		N/A	N/A
	terrace	N/A	27/4	
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	2.0 & 1.50 m	N/A	N/A
3.	Compartmentation	-10 33 1.50 III	2.0 & 1.50 m	MR
	Fire check door	N/A		
	Sealing of electrical shafts	CONTRACTOR OF THE PROPERTY OF	N/A	N/A
	Fire Rating of shaft door	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
1.		N/A	N/A	N/A
•••	Smoke Management System (Restaurant at Ground			
	Basements	N/A	N/A	
	Upper floors	12 ACPH	Natural Ventilation &	N/A
	Fire Extinguishers	Control Dev	Exhaust fan in kitchen	MR
	Total numbers in restaurant	T		
	Control of the Contro	08 no.'s	Provided	M/R
	• Types	ABC/CO ₂	ABC- 04 & Co2- 04	M/R
	IS marking	ISI marked	Provided	M/R
5.	First-Aid Hose Reels	11	N259	IVER
	Total numbers at each floor	1 Nos.		
	Length of hose reel hose	30 mtrs	Provided	M/R
	Nozzle diameter	5 mm	Provided	M/R
		- mm	Provided	M/R

N	حک

7.	Automatic fire detection and alarming system in restaurant			
	Type of detection and alarming system in restaurant			
	 Type of detectors Smoke/Heat Location of Main Panel 	N/A	Provided	N/A
	Location of Repeater Panel	N/A	At exit	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A N/A	Provided	N/A
8.	MOEFA	N/A	At exit	N/A
121		Required	Provided	M/R
	Public Address System	Required	Provided	M/R
10.	Automatic Sprinkler System		(Restaurant at Ground	CH-0000000
	Basement	N/A	N/A	7.872
	Upper floors/Restaurant Sprintly	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants		1944	N/A
F1	Size of riser/down-comer	N/A		
	 Number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	- 1121	N/A	N/A
	Total number of hydrants	1 1 1		
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	N/A	N/A	N/A
			(Restaurant at Ground f	
	Ground Level		Oldand I	iour only)
1	Discharge of main Pump	N/A	N//	
- 0	- Ivialli bumn	N/A	N/A	N/A
	 Number of main pumps Jockey Pump out put 	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A N/A	N/A
	> Pump House Access		N/A	N/A
- "		N/A	IN/A	N/A
		N/A	N/A	NUA
	Terrace level			N/A
	Discharge of pump	450 LPM	450 LPM	1
	➤ Head of the pump	40 m	40 m	M/R
	Power Supply Auto Starting of a	Required	Provided	M/R
	ruto otarting of pump	Required	Provided	M/R M/R
4. (Captive Water Storage for fire-fighting			IVIX
	▶ Underground tank capacity	27/4		
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	➤ Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
5. E	Exit Signage.	20,000 ltrs	20,000 ltrs	MR
	as (4)	Required	Provided	M/R
5. P	rovision of Lifts			IVIIK
	Pressurization of Lift Shaft	27/4		
	Pressurization of Lift lobby	N/A	N/A	N/A
- 1	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
•	orgnage	N/A	N/A	N/A

		3 5				
17.	Standby	power supply	Required	Provided	M/R	
18.	Refuge Area.					
	>	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19.	Fire Control Room					
	-	Detector System Panel	N/A	N/A	N/A	
	1	Flow Switch Panel	N/A	N/A	N/A	
	•	PA System Panel	N/A	N/A	N/A	
		Battery backup	N/A	N/A	N/A	
	•	Building Floor Plans	N/A	N/A	N/A	
20.		Fire Protection System for ion of special Risks, if any:	N/A	Two ABC type fire extinguisher found provided near elect. Panel.	N/A	

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection.

Note: - The restaurant running at ground floor only in a building comprised of basement (other property), ground plus three upper floors (1st, 2nd & 3rd floor used for office purpose)

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer
Name: - R.K. Yadav

Designation: - ADO (JKP)

(A) Wood

Principal Director

Cfo to Been

818 20x

ADO (SKP)

, put up

for rogn'

13 8 /200g

CFO Must

MS