

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2023/ 143

Dated:

10/03/2025

To

The Principal, Cosmos School, Harsh Vihar, Meethapur, Badarpur, New Delhi-110044.

Sub:- Regarding renewal of Fire Safety Certificate in r/o Cosmos School located at Harsh Vihar, Meethapur, Badarpur, New Delhi-110044.

Sir,

With reference to the letter bearing outdoor dairy no. 9843 dated 03.12.2024 on the subject cited above, it is informed that the said building was visited by Assistant Divisional Officer (M. Road) from this department on 05.03.2025 in the presence of Mrs. Anju (Office Staff) and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/SZ/2023/280 dated 20.07.2023 (Photocopy overleaf) has not been completely rectified till date.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take

suitable necessary action as deemed fit.

Yours fathfull

Director

Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2023/280 Dated: 20/07-12023

To

The Principal, M/s Cosmos School, Harsh Vihar, Meethapur, Badarpur, New Delhi-110044.

Sub:- Regarding issuance of Fire Safety Certificate in respect of Cosmos School located at Harsh Vihar, Meethapur, Badarpur, New Delhi-110044.

Sir,

With reference to your email dated 28.02.2023 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 11.07.2023 in the presence of Mrs. Shushila Rana (Vice Pricipal) and it was observed that the building is comprised of Ground + 3 upper floors. During inspection following shortcomings were observed:-

- 1. Alternate staircase should not be approachable through occupied area.
- 2. Hose reel found not functional.
- 3. Fire pump found not functional.
- 4. Overhand tank capacity 8,000 liters provided against the requirement of 10,000 liters.

5. Exit signages found removed.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Director

Delhi Fire Service

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.