

C/77

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/SZ/2025/1137

Dated: - 26/06/2025

To,

Sh. Birender Kumar (DBTB)
Delhi Bureau of Text Books,
25/2, Institutional Area, Pankha Road,
D- Block, Janak Puri, New Delhi- 110058.

Sub: - Regarding renewal of Fire Safety Certificate from fire safety point of view in r/o Delhi Bureau of Text Book at 25/2, Institutional Area, Pankha Road, New Delhi- 110058.

Sir,

Please refer to your letter No. Admin./DBTB/2025-26/342 dated 09.06.2025, on the subject cited above. In this connection it is to inform you that the above said building have been inspected by the officer concerned of this department, in presence of Mr. Sanjeev, on dated 23.06.2025, to check the status of the shortcomings already pointed out by this department vide letter No. F6/DFS/MS/2019/South/4555 dated 26.07.2019. During the course of inspection, it was observed that the shortcomings are not fully complied.

In view of the above, renewal of 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter.

Yours faithfully

(Atul Garg)
Director
Delhi Fire Service

7/9/24/6

C-21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2019/South 14555

Dated: 26/07/19

To,
Sh. Anil Kaushal, Secretary (DB & B),
Delhi Bureau of Text Book,
25/2, Institutional Area,
Pankha Road, New Delhi-110058.

Subject: - Regarding renewal of Fire Safety Certificate from fire safety point of view in r/o Delhi Bureau of Text Book, 25/2, Institutional Area, Pankha Road, New Delhi-110058.

Sir,

Please refer to your letter No.6913 dated 17.5.2019 on the subject cited above. In this connection it is to inform you that the above said building has been inspected by the officer concerned of this department on 11.7.2019 in presence of Sh. Anil Kaushal (Secretary) & Sh. Rajinder Kumar (Asstt. Section Officer) to see the workability of fire safety arrangements provided there in.

During the course of inspection following shortcomings have been observed:-

1. Some of the Fire extinguishers are not refilled/repared.
2. First Aid Hose reel are provided but not functional.
3. Fire Alarm System is provided but not functional.
4. Internal hydrants are provided but not functional as some of adopters are missing.
5. Fire pumps found non functional.
6. Terrace tank for firefighting is damaged due to some renovation work on terrace.

In view of the above shortcomings Fire safety certificate cannot be renewed. You are advised to rectify the shortcomings under intimation to this department for taking further necessary action. In absence of non function of fire fighting systems any loss be your risk & responsibility.

Yours faithfully,

(Anil Garg)
Chief Fire Officer

Ph. 011-23414250