## SOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/NDZ/2025/546

Dated: 07 19/2025

To,

Sh. Rajesh Aggarwal (GM/E& M), Delhi Metro Rail Corporation Ltd, Barakhamba Lane, New Delhi.

Sub: Regarding issuance of FSC in r/o M/S Delhi Metro Railway Station located at Karol Bagh, New Delhi.

Sir,

This has reference to letter no. DMRC/O&M/Fire/NOC/Line-3/2025/02/40 dated 28.02.2025, on the subject cited above. In this regard, it is to inform you that the site was visited by officer concerned of this department on dated 03.04.2025, in the presence of Sh. Sayyam jain, and observed that shortcomings issued earlier vide letter no.F6/DFS/MS/GH/NDZ/34 dated 22/01/25 (copy enclosed) have not been complied in totality.

In view of above, the case is rejected. Hence, Fire Safety Certificate (FSC) cannot be issued at this stage.

Encl : As above.

Yours faithfully

DIRECTOR

Delhi Fire Service

0/34

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/ 3 4

To,

Sh. Rajesh Aggarwal (GM/E& M), Delhi Metro Rail Corporation Ltd, Barakhamba Lane, New Delhi.

Sub: Renewal of FSC (Fire Safety Certificate) in r/o Delhi Metro Railway Station located at Karol Bagh, New Delhi.

This has reference to your NO.DMRC/S&R/FSC/L-3/2024/29 dated 07/11/2024, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officers concerned of this department on 14.01.2025 in the presence of Sh. Sayyam, Manager and following shortcomings were observed: -

Detectors found nonfunctional at some places.

3. Smoke management system is not integrated with detection /MCP.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings

for further consideration in the matter.