

No.F.6/DFS/MS/EH/2025/SZ/ 177

Dated. 08./0.5./2025

FIRE SAFETY CERTIFICATE

NEW DELHI-110001

Certified that the M/s Dhaba Estd 1986 Delhi Situated at Ground floor, Property no 04, World Mark-2, Aerocity, New Delhi 110037 in the building comprised of 03 tier Basement, Ground, Mezzanine + 06 Upper floor owned/occupied by A Unit of AZURE hospitality Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2022/SZ/58 Dated 03/06/2022. The premise was re-inspected by the officer concerned of this department on 29/04/2025 in the presence of Mr. Mohit Kumar and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant at ground floor) and validity upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>08/05</u>/2025 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch 1st Floor PS Defence Colony New Delhi 110049 (Ref. MCD Portal ID No 2025032604613 Dated 18/04/2025)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



| 1,2 | | \vdash | INSPECT | ION REPORT | | | |
|-----|--------------------------------------|----------|---|---|---------------------------------------|------------|--|
| Y | No | me d | Address of the Building | | | | |
| 1 | Na | | or the Building | M/s Dhaba Estd 1986 Delhi (A Unit of AZURE | | | |
| | | 1 | | nospitality Pvt L | Ltd) at Property no 04 Ground floor | | |
| // | - | | 600 | World Mark-2, A | erocity, New Delhi 11003 | 7 | |
| 2 | | - | f Occupancy | Group-D Assemb | oly Building (Restaurant | ot CE) | |
| 3 | Building Comprised of | | | Group-D Assembly Building. (Restaurant at GF) 03 Basements, Ground Mezzanine + 06 Upper Floors | | | |
| 4 | | • | f Case | Renewal | ound Mezzanine + 06 Up | per Floors | |
| 5 | De | etails | of Previous NOC | | 0022/57/59 Date 1 02/04/10 | 000 | |
| 6 | Fire Safety Directives Letter No | | | F6/DFS/MS/EH/2022/SZ/58 Dated 03/06/2022 | | | |
| 7 | Date of Inspection | | | F6/DFS/MS/Mixed/SZ/2020/533 dated 21/12/2020 29/04/2025 | | | |
| 8 | Name of the Inspecting Officers | | | Sh. Suman Kumar ADO | | | |
| 9 | | | & Designation of Officers | Mr. Mohit Kumar | | | |
| | 1 | | he building side | Mir. Monit Kumar | , | | |
| 10 | | | of construction | 2000 | <u> </u> | | |
| 11 | Applicant letter No. | | | 2009 MCD Portal ID No 2025032604613 Dated 18/04/2025 | | | |
| S. | Minimum standards on Fire Prevention | | | | | Remarks | |
| No. | a | nd l | Fire Safety U/R 33 | UBBL/NBC Requirements | Provided at Site | MR/NMR | |
| 1 | | | | Requirements 8 F 6/DFS/MS/Mi | xed/SZ/2023/29 Dt. 18/12/2 | | |
| | | | Road width | Restt. within | Provided by Mall | MR | |
| | | | Gate width | Worldmark-2 | N/A | N/A | |
| | | | Width of internal road | Aerocity | N/A | N/A | |
| 2 | | | iber, width, type & arrangement of exit | S. | | | |
| | + | - | Number of Staircase | | aintained by the Bldg Man As above | MR | |
| | | - 1 | Upper floors.Basement floor. | Restt within Mall N/A | N/A | N/A | |
| | + | _ | Width of Staircase | | aintained by the Bldg Mar | nagement | |
| | T | -, | > Upper floors | Restt within Mall | As above | MR | |
| | | ļ. | > Basement floor | N/A | N/A | N/A | |
| | 1 | c) | Protection of exits | D 0 1411-14-11 | A. shave | MR | |
| | | | Fire check doorPressurization | Restt within Mall Restt within Mall | As above As above | MR | |
| | ł | d) | No. of continuous staircase to terrace | Restt within Mall | -NA- | MR | |
| | | | Width of corridor | N/A | N/A | N/A | |
| | | f) | Door size | 02 required | 2 mtr & 2mtr | MR | |
| | 3 | Co | mpartmentation. | Provided & Ma | aintained by the Bldg Mar | | |
| | | | Fire check door.Sealing of electrical shafts. | N/A | As above As above | MR | |
| | | | • Fire rating of shaft door. | N/A | As above As above | MR N/A | |
| | | | Water curtain | N/A | As above | N/A | |
| | | | Fire dampers. | N/A | As above | N/A | |
| | 4 | Sm | oke Management system. | Provided & Ma | aintained by the Bldg Mar | agement | |
| | | | Basement | 30 ACPH | N/A | N/A | |
| | 5 | Di. | Upper floors Extinguishers. | 12 ACPH | Exhaust Fans Provided | MR | |
| | 3 | FII | Total numbers | Required | 08 Nos | MR | |
| | | | Types | ABC/CO ₂ | ABC & CO ₂ | MR | |
| | | | ISI Marking | Required | Provided | MR | |
| | 6 | Fi | st Aid Hose Reels. | | aintained by the Bldg Man | | |
| | | | Total numbers on each floor. Length of hose-reel hose. | One near Restt 30m | As above As above | MR | |
| | | | Nozzle Diameter | 5mm | As above | MR MR | |
| | 7 | Aı | tomatic fire detection & alarming system | | aintained by the Bldg Mar | | |
| | | | Type of detectors | Required | Smoke & heat | MR | |
| | | | Location of Main Panel | Required | As above | MR | |
| | | | Location of Repeater Panel | Required | As above | MR | |
| | | | Alternate source of power | Required | As above | MR | |
| | 8 | N/I | Hooter's location OEFA | Required | As above | MR | |
| - | 9 | _ | OLFA blic Address System | Required | Provided | MR | |
| | , | r | Duc Address System | N/A | | MR | |

| Г | No | · I) | | S 2 |
|---------------|--|---|--------------------------------------|--------------|
| - | 10 Automatic Sprinkler System | Provided & Mai | ntained by the Bldg Mana As above | gement MR MR |
| | Basement | Required | As above | MR |
| | Ground floor. | Required | As above | MR 9 |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| | 11 Internal Hydrants. | | ntained by the Bldg Mana As above | N/A |
| | Size of Riser/Down-comer | N/A | As above | N/A |
| | Number of Hydrant per floor | N/A | As above | N/A |
| | Hose box. | N/A | ntained by the Bldg Mana | |
| | 12 Yard Hydrants. | Provided & Mai | As above | N/A |
| | Total number of hydrants. | N/A N/A | As above | N/A |
| | Hose box. | Drovided & Mai | ntained by the Bldg Man | agement |
| | 13 Pumping arrangements. | Provided & Maintained by the Bldg Management Common pumping arrangements for entire bldg | | |
| | Ground Level | N/A | 22800 LPM | N/A |
| | Discharge of main pump. | N/A N/A | 105m | N/A |
| | Head of main pump. | N/A N/A | 02 Nos. | N/A |
| | Number of main pumps. | N/A N/A | 180 LPM | N/A |
| | Jockey Pump output. | N/A N/A | 105m | N/A |
| | > Jockey Pump head. | N/A N/A | 22800 LPM | N/A |
| | Standby Pump output. | N/A N/A | 105m | N/A |
| | Standby Pump head. | N/A N/A | Provided | N/A |
| | Auto Starting/Manual Stopping. | N/A N/A | Provided | N/A |
| | Pump house access. | IN/A | ******** | |
| | Terrace Level | 450 LPM | As above | MR |
| | Discharge of pump. | 450 LPM 40 m | As above | MR |
| | ➤ Head of pump. | | As above | MR |
| | Power supply. | Required | As above | MR |
| | Auto starting of pump. | Required & Mai | ntained by the Bldg Ma | |
| 14 | | | 1,00,000 Ltrs | MR |
| | Underground tank capacity. | Required | Provided | MR |
| | Draw-off connection. | Required | | MR |
| | Fire Service Inlet. | Required | Provided | |
| | Access to tank. | Required | Provided | MR |
| | Overhead tank capacity. | Required | 20,000 Ltrs | MR |
| 15 | Exit Signage. | Required | Provided . | MR |
| 6 | Provision of Lifts. | Provided & Maintained by the Bldg Management | | |
| U | Pressurization of lift shaft. | N/A | As above | N/A |
| | 1 | N/A | As above | N/A |
| | Pressurization of lift lobby. | | | |
| | Communication in lift car. | N/A | As above | N/A |
| | Fireman's switch. | N/A | As above | N/A |
| | • Lift signage. | N/A | As above | N/A |
| + | Standby Power Supply | Required | Provided | MR |
| \rightarrow | | required | 11011000 | IVII |
| 1 | Refuge Area | 37/1 | | - |
| | Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |
| F | Fire Control Room. | Provided & Ma | | |
| + | | Provided & Maintained by the Bldg Management | | |
| | Detector system panel. | N/A | As above | N/A |
| | Flow switch panel. | N/A | As above | N/A |
| | DA | N/A | As above | - |
| | PA system panel. | | As above | N/ |
| | | NI/A | | |
| | Battery backup. | N/A | As above | N/ |
| | Battery backup.Building floor plan. | N/A N/A | | N/ |
| Spe | Battery backup.Building floor plan. | N/A | As above | N/ N/ |
| | Battery backup. | | | - |

n1-12

आज़ादी का अमृत महोत्सव

The fire protection system provided in the building were randomly checked and found at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2022/SZ/58 Dated 03/06/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

100 of 2025

Signature of the Inspecting Officer

Name: Sh. Suman Kumar

Designation: ADO

DO (Sp)

fmuls yeps

2 5 2025

Dênceta

17n/5/m

bleare uplead

08/05/2025

MS Cell

09/8/25

 \oplus