

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

राय पात ।

No. F.6/DFS/MS/Hospital/SZ/2025/ 1593

Dated: | 0 / 09 /2025

To

Col. Digvijay Singh (CSO), Administrative Block, AIIMS, Ansari Nagar, New Delhi–110029

Sub: Renewal of Fire Safety Certificate in r/o Dining Block, AIIMS Complex, Ansari Nagar, New Delhi-110029

Sir,

This is with reference to your letter No. Nil dated 05/06/2025 received in this department vide outdoor diary No. 4760 dated 12/08/2025, on the subject cited above. In this connection, it is to inform you that the premise was re-visited by the officer concerned of this department on 30/08/2025 in presence of Mr. Salesh Kumar (ASO) to verify the compliance of shortcomings issued by this office vide letter No. F.6/DFS/MS/Hospital/2024/SZ/210 dated 06/05/2025 and observed that the shortcomings as mentioned below is not yet complied.

1. Lift under installation.

In view of the above, the application for renewal of fire safety certificate cannot be considered at this stage & rejected. You are requested to rectify the above-mentioned shortcomings under intimation to this department for further action in the matter.

Yours faithfully,

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to: -

1. The Director, All India Institute of Medical Sciences, Ansari Nagar, New Delhi-110029





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/Hospital/2024/SZ/210

Dated: 06 / 05 /2025

To

Sh. Salesh Kumar, ASO (Fire Safety), Administrative Block, AIIMS, New Delhi–110029

Sub: Renewal of Fire Safety Certificate in r/o Dinning Block, AIIMS Complex, Ansari Nagar, New Delhi-110029

Sir,

This is with reference to the email received from Id: salesh@aiims.gov.in dated 05/03/2025, on the subject cited above. In this connection, it is to inform you that the said premise was inspected by the officer concerned of this department on dated 26/04/2025 to see the performance of fire protection measure in the presence of Sh. Harinder Singh (Dy. CSO). During the inspection, the shortcomings observed are as below.

- 1. Electrical shaft found unsealed vertically & horizontally at some levels.
- 2. Smoke exhaust system in basement found non-functional.
- 3. First Aid hose-reel found non-functional.
- 4. Automatic fire detection system found non-functional at some places.
- 5. Manually operated electrical call points found non-functional.
- 6. Automatic sprinkler system needs to be extended in left out area in basement.
- 7. Hose boxes near internal and external hydrants found without hoses & branch.
- 8. Lift was under installation.

In view of the above, the application for renewal of Fire Safety Certificate is rejected. You are advised to rectify the shortcomings under intimation to this department for further action in the matter.

Yours faithfully,

(ATVL GARG)
DIRECTOR

Ph 011-23414000

Copy to: -

1. The Director, All India Institute of Medical Science, Ansari Nagar, New Delhi-110029