

c/121

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/2025 | 07

Dated:- 03/01/2025

To,

The Manager
M/S East Inn Hotel,
E-364, Nirman Vihar,
Vikas Marg, Delhi.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o East Inn Hotel, E-364, Nirman Vihar, Vikas Marg, Delhi.

Sir,

This has reference to on line ID No. 2024120917796 dated 09/12/24, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 26/12/24 in the presence of Mr. Siddiqui and following shortcomings were observed:

1. CO- detector found non functional.
2. Smoke management system is provided as per gazette notification dated 27.05.2019.
3. Pump found nonfunctional.
4. PA system found nonfunctional.
5. Third floor is not allowed in previous FSC as per undertaking; whereas you have applied for 04 guest room at third floor, please clarify.
6. The basement is being used for showroom where as in previous FSC basement was allowed for storage only as per building plan.

In view of above e, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage due to above shortcomings. Therefore, you are requested to rectify/ clarify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:

Addl. Commissioner of Police (Lic), 1st floor, Defence Colony Police Station, New Delhi.