

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/GH/2025/13.5

Dated: 18/03/2025

FIRE SAFETY CERTIFICATE

Certified that the East Inn Hotel Located at E-364, Nirman Vihar, Vikas Marg, Delhi-110092. Building comprised of Basement + Ground + Mezzanine + 03 Upper Floors, Basement (Store), Ground Floor (Shops & Reception), Mezzanine (Office), First Floor (06 guest rooms) & Second Floor (05 guest rooms) Total 11 guest rooms, was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/NDZ/2021/554 dated 30/12/2021. The said premise was re-inspected by the officer concerned of this department on 05/03/2025 in the presence of Sh. Ansar Ahmed Siddiqui (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy "Residential" Group-A, Sub Division A-1 as above, total 11 guest rooms up to 2nd floor only with effect from 18/2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 18/03/2025 at New Delhi by

Director Tel No. 011-23414000

Copy to:-

1. The Joint Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi: in r/o computer id no. 2025021201767dated 12/02/2025

2. The Authorized Signatory, East Inn Hotel, E-364, Nirman Vihar, Vikas Marg, Delhi-110092

Conditions for the validity of fire safety certificate:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

9. Kitchen shall not be allowed in guest house building.

10. Any flammable material for interior decoration is prohibited.

11. The guest house management has given an undertaking that there is no use of 3rd floor of their hotel. 3rd floor is closed and not being use in hotel. If they found using of 3th floor then their FSC may be treated as null & void.

INSPECTION REPORT

Name & address of the building : East Inn, located at E-364, Nirman Vihar, Vikas
Marg, Delhi

Type of Occupancy

: Residential Building "Group-A", Basement + Ground

Mezzanine + 03 Upper floors

: Renewal

3. Type of Case

: F.6/DFS/MS/GH/NDZ/2021/554 dated 30/12/2021

4. Details of previous NOC 5. Fire Safety directives Letter No.

: N/A

Total guest rooms: - 11 nos.

6. Date of inspection

: 05/03/2025

Basement: - store GF - shops & reception Mezz. Floor - office 1st floor - 06 guest rooms

7. Name of the Inspecting Officer

: Aman Kumar Lathar, ADO (JWP)

2nd floor – 05 guest rooms

8. Name and designation of Officer

3rd floor - Sealed

from the building side

: Sh. Ansar Ahmed Siddiqui (Manager)

9. Year of Construction

: 1989 (As mentioned in online application)

10. Applicant's online application no. : 2025021201767dated 12/02/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements Existing fire safe arrangements	Provided site	at Remarks MR/NMR			
1.	Access of building	06 m	06 m	MR			
1	Road width	NA	NA	NA			
	Gate width	NA NA	NA	NA			
	Width of internal road						
2.	Number width, Type & Arrangements of CARS						
-	a. Number of staircases	02 nos.	Provided	MR			
	 Upper floors 	01 no.	Provided	MR			
	 Basements 	OT NO.					
	b. Width of staircases	0.90 m 0.90 m & 0.70 m		MR (old case)			
	 Upper floors 	0.90 m	2.0 m	MR			
	 Basements 	0.70 III					
	c. Protection of exits	Davised	Provided	MR			
	 Fire check door 	Required	NA	NA			
	 Pressurization 	NA 01	Provided	MR			
	d. No of continuous staircase	01					
	to terrace	1.50 m	Provided	MR			
	e. Width Of Corridor	1.0 m	Provided	MR			
	f. Door Size	1.0 III					
	Compartmentation	Required	Provided	MR			
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain 	NA	NA	NA			
		NA NA	NA	NA			
ı			NA	NA			
		NA NA	NA	NA			
l	Fire Dampers	NA					
1	Smoke managements System		NA	NA			
	Basements	NA	Provided	MR			
	Upper floors	Required	110.134				
+	Fire Extinguishers		Provided	MR			
+	Total numbers	12 nos.	Provided	MR			
	Types	ABC & CO ₂					
	IS marking	ISI marked	Provided	MR			
1	First – Aid Hose Reels	01	Provided	MR			
	Total numbers on each floor		Provided	MR			
	Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	05 mm	Flovided				

7.	Automatic Geo detection 1.1			
ļ':-	 Automatic fire detection and alarm Type of detectors 		Descrided	MR
	Location of Main Panel	CO type	Provided	MR
	Location of Nam Panel Location of Repeater Panel	Required	Provided	NA NA
	Alternate source of power	NA Descripted	NA Descrided	MR
1 1	Hooters' Location	Required	Provided	MR
		Required	Provided	NA NA
8.	MOEFA	NA	NA	MR
9.	Public Address System	Required	Provided	IVIN
10.	Automatic Sprinkler System		T D :1.1	MR
1 1	Basements	Required	Provided NA	NA
- 1	Upper Floor	NA NA	NA NA	NA
1.	Sprinkler above false ceiling	NA	INA	1
11.	Internal Hydrants:	NA	NΛ	NA
1 1	Size of riser/down- comer	NA NA	NA NA	NA
1 1	 Number of hydrants per floor 	N/A	1771	
1 1		NA	NA	NA
12 3	Hose Box	IVA		
12.	Yard Hydrants	NA	NA	NA
	Total number of hydrants	NA NA	NA NA	NA
12 5	Hose Box	INA	TAIS	
13. P	rumping Arrangements:	1		1
1 1	Ground Level	NIA	NA	NA
	Discharge of main pump	NA NA	NA NA	NA
2	> Head of main pump		NA NA	NA
=	Number of main pumps	NA NA	NA NA	NA
1	> Jockey pump out put	NA NA	NA NA	NA
	> Jockey pump head	NA NA	NA NA	NA
	Standby Pump out put		NA NA	NA
	Standby Pump HeadAuto Staring/Manual	NA NA	NA NA	NA
	Auto Staring/Manual stopping	NA	IVA	1.12.5
1		NIA -	NA	NA
	Pump House AccessTerrace level	NA -	INA	1471
	We Exemple and trail	450 1	Provided	MR
	Discharge of pumpHead of the pump	450 lpm	Provided	MR
	> Power supply	40 m	Provided	MR
1		Required	Provided	MR
		Required	Provided	IVIIX
4. Car	otive water Storage for fire fighting	31.	NIA	NA
	 Under ground tank capacity 	NA	NA NA	NA NA
	> Draw off connection	NA	NA	
	Fire service inlet	NA	NA	NA
1	Access to tank	NA	NA	NA
	Overhead Tank capacity	8, 000 ltrs.	Provided	MR
5 Exit	Signage	Required	Provided	MR
Dear	rision of Lifts			
		NA	NA	NA
>	Pressurization of Lift Shaft	NA NA	NA	NA
>	Pressurization of lift lobby		NA	NA
>	Communication in lift Car	NA	NA NA	NA
P	The state of the s	NA	22.20(2.20)	NA NA
>		NA	NA III	MR
Stand	by power supply	Required	Provided	IVIK
	ge Area			NOTION.
-		NA	NA	NA
A	1	NA	_ NA	NA
1	Location			
Fire c	ontrol room	NA	NA	NA
>	Detector system panel		NA	NA
-	Flow Switch Panel	NA		NA
11 0.55	PA System Panel	NA	NA	NA
	Battery backup	NA	NA	
1		NIA	NA	NA
A A	Building Floor Plans	NA/		

Special Fire Protection Systems for NA NA NA Protection of special Risks, if any; Note:- Sh. Ansar Ahmed Siddiqui (owner) of East Inn Hotel has given an undertaking that there is no use of third floor of our hotel. Third Floor is closed and not being use in Hotel. The fire protection systems provided in the building were checked and found functional at the time of inspection. Shortcoming issued vide letter no. F6/DFS/MS/GH/NDZ/2025/07 dated 03/01/2025 found rectified. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F.6/DFS/MS/GH/NDZ/2021/554 dated 30/12/2021, renewal under rule 35 of the Delhi Fire Service Rule 2010, is recommended. Accordingly, DFA is put up for approval & signature please. ADO (JWP)