



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Dated: 21/05/2025

No. F6/DFS/MS/School/2025/NDZ/ 418

To,

The Principal,
MCD Primary School,
C-1, Yamuna Vihar (II nd Shift),
Delhi – 110053.

Sub.: - Inspection Report in r/o MCD Primary School located at C-1, Yamuna Vihar (IInd Shift), Delhi – 110053.

Sir,

Please refer to your outdoor diary No. 1024 dated 25/04/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 14/05/2024 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2018/2384 dated 30/05/2018 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

(ATUL GARG)
DIRECTOR

o/c DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, Municipal Corporation of Delhi, Plot No.419, Patparganj Industrial Area, Delhi - 110092.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/School/2018/ 2384

Dated: 30/5/18

To,

The Principal,
EDMC Prathibha Vidyalaya,
C-1, Yamuna Vihar,
Delhi 110053

Sub:- Regarding Issuance of Fire Safety Certificate.

Sir,

This is in reference to your letter No. nil dated 19/02/18 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mrs. Chitra Pravin, Principal of the School on 10/05/2018. During the course of inspection, the following points / shortcomings were noticed in the building comprised of ground plus two upper floors.

1. Only 02 fire extinguishers provided in place of 06 fire extinguishers as required.
2. First-Aid hose reel (01 nos.) at each floor not provided.
3. A fire pump having 450 LPM output at 40 meters head not provided.
4. Over Head water storage tank 10,000 liters capacity exclusively for fire fighting not provided at terrace.
5. Exit Signage not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully

(Vipin Kental)
Chief Fire Officer

o/c

h

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92