

C 9.6

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001**


No. F6/DFS/MS/EH/SZ/2025/381

Dated: 19 / 11 / 2025

**FIRE SAFETY CERTIFICATE**

Certified that the M/s Fam Jam Restaurant (A Unit of Vashisth Enterprises) located at Plot No. 3, First Floor, MLU Manish Twin Plaza-II, Dwarka, Delhi - 110078, in the building comprised of Ground + 03 upper floors but restaurant is running at 1<sup>st</sup> floor only was granted FSC by this department vide letter no. F6/DFS/MS/SZ/2022/EH/309 dated 04.11.2022. The building/premises was re-inspected by officer concerned of this department on 07.11.2025 in presence of Mr. B. R. Roy (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. Accordingly, the premises is fit for occupancy of class "Assembly Building" (Group-D), restaurant is running at 1<sup>st</sup> floor only, with effect from .....19.11.2025... for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 subject to condition printed below.

Issued on .....19.11.2025.....at New Delhi by

  
17/11/25  
(A. K. Malik)  
Dy. Chief Fire Officer  
Delhi Fire Service  
def

**Copy to:-**

1. The Commissioner, MCD, Dr. SPM Civic Centre, New Delhi - 110002. w.r.to ID No. 2025102314322 dated 23.10.2025.
2. The Licensee, M/s Fam Jam Restaurant (A Unit of Vashisth Enterprises) at Plot No. 3, First Floor, MLU Manish Twin Plaza-II, Dwarka, Delhi - 110078.

**Conditions for the validity of fire safety certificate**

1. This FSC is valid for first floor (restaurant) only.
2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
4. The trained fire fighting staff should be available round the clock.
5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
9. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.



## INSPECTION REPORT

1	Name & address of the building	M/s Fam Jam Restaurant (A Unit of Vashisth Enterprises) located at Plot No. 3, First Floor, MLU Manish Twin Plaza-II, Dwarka, Delhi - 110078.		
2	Building is comprised of	Ground + 03 upper floors (But restaurant is running at 1 <sup>st</sup> floor only)		
3	Type of occupancy	Assembly (Restaurant)		
4	Type of case	Renewal		
5	Details of previous FSC	F6/DFS/MS/SZ/2022/EH/309 dated 04.11.2022		
6	Fire safety direction letter no.	Nil		
7	Date of inspection	07.11.2025		
8	Name of the inspecting officers	Suman Kumar, ADO (SPM)		
9	Name of the designation of officer from the building side	Mr. R. B. Roy (Manager)		
10	Year of construction	Before 2009		
11	Applicant's letter no.	Online application ID No. 2025102314322 dated 23.10.2025		
S.No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	As per Old FSC dated 04.11.2022	Provided at Site	Remarks MR/ NMR
1	<b>Access To Building:</b>			
	Road width	09 m	Provided	MR
	Gate width	4.5 m	Directly accessible from road	MR
	Width of internal road	NA	NA	NA
2	<b>Number, Width, Type and Arrangement of Exits:</b>			
	<b>A</b> Number of staircases			
	a Upper floor	01 no.	01 no.	MR (being old case)
	b Basement	NA	NA	NA
	<b>B</b> Width of staircases			
	a Upper floor	1.25 m	Old case	MR (being old case)
	b Basement	NA	NA	NA
	<b>C</b> Protection of exits			
	a Fire check door	NA	NA	NA
	b Pressurization	NA	NA	NA
	<b>D</b> No. of continuous staircases to terrace	Required	01 no.	MR
	<b>E</b> Width of corridor	NA	NA	NA
	<b>F</b> Door size	1.20 m & 1.0 m	Old case	MR (being old case)
3	<b>Compartmentation:</b>			
	<b>A</b> Fire check door	NA	NA	NA
	<b>B</b> Sealing of electrical shafts	NA	NA	NA
	<b>C</b> Fire rating of shaft door	NA	NA	NA
	<b>D</b> Water curtain	NA	NA	NA
	<b>E</b> Fire dampers	NA	NA	NA
4	<b>Smoke Management System:</b>			
	<b>A</b> Upper floors	Required	Exhaust fans	MR
	<b>B</b> Basements	NA	NA	NA

(M/s Fam Jam Restaurant (A Unit of Vashisth Enterprises) at Plot No. 3, 1<sup>st</sup> Floor, MLU Manish Twin Plaza-II, Dwarka, Delhi - 110078)

<b>5.</b>	<b>Fire Extinguisher:</b>				
	<b>A</b>	Total numbers	06 nos.	Provided	<b>MR</b>
	<b>B</b>	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	<b>MR</b>
	<b>C</b>	ISI marking	Required	Provided	<b>MR</b>
<b>6</b>	<b>First-Aid-Hose Reels:</b>				
	<b>A</b>	Total numbers of each floor	01 no.	Provided	<b>MR</b>
	<b>B</b>	Length of hose reel hose	30 m	Provided	<b>MR</b>
	<b>C</b>	Nozzle diameter	05 mm	Provided	<b>MR</b>
<b>7</b>	<b>Automatic Fire Detection And Alarming System:</b>				
	<b>A</b>	Type of detectors	NA	NA	NA
	<b>B</b>	Location of main panel	NA	NA	NA
	<b>C</b>	Location of repeater panel	NA	NA	NA
	<b>D</b>	Alternate source of power	NA	NA	NA
	<b>E</b>	Hooters	NA	NA	NA
<b>8</b>	<b>MOEFA:</b>		Required	Provided	<b>MR</b>
<b>9</b>	<b>Public Address System:</b>		NA	NA	NA
<b>10</b>	<b>Automatic Sprinkler System:</b>				
	<b>A</b>	Basement	NA	NA	NA
	<b>B</b>	Upper floor	Required	Provided in restaurant	<b>MR</b>
	<b>C</b>	Sprinkler above false ceiling	NA	NA	NA
<b>11</b>	<b>Internal Hydrants:</b>				
	<b>A</b>	size of riser/down-comer	100 mm	Provided	<b>MR</b>
	<b>B</b>	Number of hydrants per floor	01 no.	Provided	<b>MR</b>
	<b>C</b>	Hose box	Required	Provided	<b>MR</b>
<b>12</b>	<b>Yard Hydrants:</b>				
	<b>A</b>	Total number of hydrants	NA	NA	NA
	<b>B</b>	Hose box	NA	NA	NA
<b>13</b>	<b>Pumping Arrangements:</b>				
	<b>A</b>	Ground level			
	a)	Discharge of main pump	NA	NA	NA
	b)	Head of main pump	NA	NA	NA
	c)	Number of main pumps	NA	NA	NA
	d)	Jockey pump out put	NA	NA	NA
	e)	Jockey pump head	NA	NA	NA
	f)	Standby pump out put	NA	NA	NA
	g)	Standby pump head	NA	NA	NA
	h)	Auto starting /manual stopping	NA	NA	NA
	i)	Pump house access	NA	NA	NA
	<b>B</b>	Terrace level			
	a)	Discharge of pump	450 LPM, 180 LPM	Provided	<b>MR</b>
	b)	Head of the pump	35 m	Provided	<b>MR</b>
	c)	Power supply	Required	Provided	<b>MR</b>
	d)	Auto starting of pump	Required	Provided	<b>MR</b>

(M/s Fam Jam Restaurant (A Unit of Vashisth Enterprises) at Plot No. 3, 1<sup>st</sup> Floor, MLU Manish Twin Plaza-II, Dwarka, Delhi – 110078)



14	<b>Captive Water Storage For Fire Fighting:</b>			
	A	Underground tank capacity	NA	NA
	B	Draw-off connection	NA	NA
	C	Fire service inlet	NA	NA
	D	Access to tank	NA	NA
	E	Overhead tank capacity	5,000 ltrs.	Provided
15	<b>Exit Signage:</b>		Required	Provided
16	<b>Provision of Lifts:</b>			
	A	Pressurization of lift shaft	NA	NA
	B	Pressurization of lift lobby	NA	NA
	C	Communication in lift car	NA	NA
	D	Firemen's grounding switch	NA	NA
	E	Lift signage	NA	NA
17	<b>Standby Power Supply:</b>		Required	DG Set
18	<b>Refuge Area:</b>			
	A	Total area	NA	NA
	B	Location	NA	NA
19	<b>Fire Control Room :</b>			
	A	Detector system panel	NA	NA
	B	Flow switch panel	NA	NA
	C	Pa system panel	NA	NA
	D	Battery backup	NA	NA
	E	Building floor plans	NA	NA
20	<b>Special Fire Protection Systems For Protection of Special Risks, If Any:</b>		ABC fire extinguishers provided near electric panel	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No F6/DFS/MS/SZ/2022/EH/309 dated 04.11.2022 is recommended to be renewed (restaurant at 1<sup>st</sup> floor only), under Rule 37 of the Delhi Fire Service Rules 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer  
Name Suman Kumar  
Designation ADO (SPM)

DO (SW)


By:  10/11/25  
RAJINDER ATWAL

By:  11/11/25  
MALIK

Principal Director

By:  11/11/25

By:  11/11/25

By:  14/11  
DO (SW) 17/11  
ADO (SPM)