

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/GH/2025/SZ/ 400

Dated: 22/09 /2025

To,

The Commissioner,
Municipal Corporation of Delhi,
E-1, 9th Floor, Dr. SPM Civic Centre,
Minto Road, New Delhi-110002

Sub: Regarding issuance of Fire Safety Certificate in r/o M/s GLORY located at Kh. No 410, Road No-4, Street No 7, Mahipalpur New Delhi 110037

Sir,

This has reference with your MCD Portal ID 2025072811970 dated 07/09/2025 on the subject cited above. In this connection, it is to inform you that the above-mentioned premise was visited by the officer concerned of this department on 11/09/2025 in the presence of Ms. Pooja (Manager) and observed that the shortcoming intimated vide letter of even no 22 dated 17/01/2024 has not been complied yet.

In view of above observations, the application for issuance Fire Safety Certificate **is rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

Encl: - As above


(VIRENDRA SINGH)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI

cl/6

G-8

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

Dated: 17/01/2024

No. F.6/DFS/MS/GH/2024/SZ/ 22
To

The Joint Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony,
New Delhi 110049

Sub: Regarding issuance of FSC in r/o M/s GLORY located at Kh. No 410, Road No-4,
Street No 7, Mahipalpur New Delhi 110037

Sir,

This has reference with **MHA Portal ID 2023120819373 Dated 19/12/2023** on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 16/01/2024 in the presence of Ms. Jiya (Manager) of the Guest House. Accordingly fire safety arrangement were tested / checked and found following observation.

1. There are two staircase having with of 1.50 mtr & 1.35 mtr against the required with of 1.50 mtr each.
2. The width of corridor is 1.35 mtr against the required width shall be 1.50 mtr for single loaded and 1.80 mtr for double loaded as per clause 7.11.2 of UBBL 2016.
3. Smoke ventilation system not provided in the building as per clause 7.31 of UBBL 2016.
4. First aid hose reel provided but found not functional.
5. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
6. Internal hydrant system not provided.
7. Terrace level pumps capacity 450 LPM not working.
8. Overhead tank capacity 6000 ltrs provided against the required capacity of 10,000 ltrs & fire fighting tank are not dedicated.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE