

0/13



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/School/SZ/2025/ 881

Dated: 12/12/2025

To,

The Principal,  
Govt. Boys Senior Sec. School  
Malviya Nagar, New Delhi-110017.

Sub: Regarding issuance of Fire Safety Certificate in r/o Govt. Boys Senior Sec. School located at Malviya Nagar, New Delhi - 110017.

Sir,

This has reference to your letter no. GBSSS/MVN/EM/2025-26/323 dated 20/11/2025 received in this department through outdoor diary no. 8554 dated 20.11.2025, on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 04/12/2025 in the presence of Sh. Laxmi Kant (Principal) and observed that the observation issued by this department vide letter no. F6/DFS/MS/School/2019/SZ/3528 dated 13/06/2019 (copy overleaf) has still not complied so far.

In view of above, the application for issuance of Fire Safety Certificate is rejected. Further, the occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Encl: as above.

Yours faithfully,

  
(A.K. Malik)  
Dy. Chief Fire Officer  
Delhi Fire Service  
o/c @

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

Dated: ...13/06/19

No. F.6/DFS/MS/School/2019/SZ/ 3528

To

The Vice Principal/HOS,  
Govt. Boys Senior Sec. School,  
Malviya Nagar, New Delhi-110017

Sub: - Regarding issuance of Fire Safety Certificate (FSC).

Sir,

This is in reference with your letter No. GBSSS/MVN/EM/2018-19/51 dated 02-03-2019 received through outdoor diary No. 5344 dated 02/03/2019 on the subject cited above. In this connection, the school premise was visited by officer concern of this department on 27/05/2019 in your presence to verify the status of fire prevention and fire safety measures provided therein. During the inspection it was observed that the school has three building blocks. A & B (Old) blocks comprised of Ground + 2 upper floors and C block (New) comprised of Ground + 3 upper floors, B & C blocks are interconnected upto 2nd floor. The shortcomings observed are as below:

1. Single staircase found provided from 2<sup>nd</sup> to 3<sup>rd</sup> floor in C block against required two numbers.
2. First aid hose reel in A & B block not provided and hose reel in C block found nonfunctional.
3. Fire pump at terrace of 450 LPM capacity against 40m head not provided in A & B block and terrace pump provided in C block found non-functional.
4. Overhead tank capacity 10,000 liters exclusively for fire-fighting each in A & B block not provided.
5. Exit sign not provided.

In view of above shortcomings, issuance of FSC cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further consideration in the matter.

Yours faithfully,

(Atul Garg)

Chief Fire Officer  
Tel.011-23414250

Copy to: -

1. The Dy. Director of Education (South),  
Directorate of Education (District South),  
Sector-3, RK Puram, New Delhi-110022