## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/EH/2025/SZ/8.3

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Haldiram Products Pvt Ltd, located at Ground & Mezzanine floor, 5A, 6, 7, D-Mall, Sector 10, Rohini, Delhi 110085 in the building comprised of 03 Tire Basement, Ground plus Five Upper Floor owned/occupied by M/s Haldiram Products Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/2022/WZ/EH/29 dated 04/02/2022. The restaurant premise was re-inspected by the officer concerned of this department on 27/02/2025 in the presence of Mr. Rahul Kumar and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-D Assembly Building" (Restaurant for Ground & Mezzanine Floor only) and validity upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on  $\frac{06}{\sqrt{03}}/2025$  at New Delhi by

(ATOIL GARG) DIRECTOR

DELHI FIRE SERVICE

Copy to: -

 The Addl. Commissioner of Police, PS Defence Colony, New Delhi 110049. (Ref. MCD Portal 2025021401880 dated 14/02/2025)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

 All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system

4. The basement shall be used as per the provisions of BBL/NBC Part- IV.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

N/27

1	Name & Address Col. 70 1111	ION REPORT	आज़ादी	क्रा		
_	Address of the Building	M/s Haldiram Products Put I to कार्या				
2	Type of Opposite	Sector 10, Rohini, Delhi.				
3	The state of the s	Assembly Building Fating house of CD 6 24				
4	J PC UI I BCo					
2	Details of Pressions MOC	Kenewai				
6	Fire Safety Directives Letter No	F6/DFS/MS/2022/WZ/EH/29 dated 04/02/2022				
7	Date of Inspection	- 5/21 5/1415/2024/ W//174 detail 10/13/2024 Q 4 113/2				
8	Name of the Inspecting Officers	2110212025				
9	Name & Designation of Officers	ADO (BCP)				
1 10	from the building side	Mr. Rahul				
10	Year of construction	the Language of the page of the				
11	Applicant letter No.	2006				
S. No.		MCD Portal 2025021401880 dated 14/02/2025				
~ 140'	Minimum standards on Fire Prevention	The state of the s				
1	- LIC GRIPPO II/D 44	Old NOC	Provided at Site	Remarks		
	Access to Building.	Requirements		10000		
	Road width	F6/DFS/MS/2024/	WZ/724 dated 10/12/202	4 (Mall /NOC)		
	Gate width	12 mtr	Provided*	MR		
		Accessible	Provided*			
-	Width of internal road	06 mtr		MR		
11 2	Number, width, type & arrangement of ex	Wilden J	Provided*	MR		
Xivi	a) Number of Saci	its. in de	P Region			
	a) Number of Staircase  > Upper floors.	Provided & Maintained by Mall				
	> Basement floor.	02 Nos	Provided*	MR		
	b) Width of Ca.	N/A	N/A	N/A		
	> Upper floors	Prov	ided & Maintained by	Moll N/A		
A	Basement floor	02 mtr each	Provided*	MR		
	c) Protection of exits	N/A	N/A	N/A		
	> Fire check door	Prov	ided & Maintained by	Moll N/A		
	> Pressurization	Required	Provided*	MR		
		Required	Provided*			
	d) No. of continuous staircase to terrace	Required	Provided*	MR		
	c) width of corridor	Required	Provided*	MR		
4.7	f) Door size	1.50m x 2		MR		
3	Compartmentation.	21/21/	1.50 m & 1.50m	MR		
1	Fire check door.	Provided & Maintained by Mall				
	Sealing of electrical shafts.	Required	Provided*	MR		
	Fire rating of shaft door.	Required	Provided*	MR		
	Water curtain	Required	Provided*	MR		
	Fire dampers.	N/A	N/A	N/A		
4	Smoke Management system.	N/A	N/A	NI/A		
	Basement	Provided & Maintained by Mall				
	Upper floors	30 ACPH	Provided*			
5	Fire Extinguishers.	12 ACPH	Provided*	MR		
	1,		CLINE DAMES ATTACKED	MR		
	Total numbers	Required	0011 66 1	21		
	Types	ABC/CO <sub>2</sub>	05 Nos	MR		
UL.	ISI Marking	ISI marked	ABC-07 & CO <sub>2</sub> -03	MR		
. 6	First Aid Hose Reels.		Provided	MR		
	Total numbers on each floor.	Provided & Maintained by TDI Mall				
	<ul> <li>Length of hose-reel hose.</li> </ul>	30m	Provided*	MR		
14	Nozzle Diameter		Provided*	MR		
3	And the second s	5mm	Provided*			
7	Automatic fire detection & alarming system  Type of detectors	m. Provided a x		MR		
Jul 1		Position I Provided & Maintained by Mall				
- 3	Location of Main Panel	Required	Provided*	MR		
	Location of Repeater Panel	Required	Provided*	MR		
	Alternate source of power     Hooter's location	Required	Provided*			
		Paguine 1		MR		
		Required	Provided*	MR		
		Required	Provided*	IVIK		

1 k

	north-section and the section			• • •		
8	MOEFA	Required	Provided*	MR		
9	Public Address System	N/A	N/A	N/A		
10	Automatic Sprinkler System	Provide	d & Maintained by T	DI Mall		
3.0	Basement	Required	Provided*	MR		
	Ground floor.	Required	Provided*	MR		
	Sprinkler above false ceiling	Required	Provided*	MR		
11	nternal Hydrants. Provided & Maintained by Mall					
	Size of Riser/Down-comer	Required	Provided*	MR		
	Number of Hydrant per floor	Required	Provided*	MR		
	Hose box.	Required	Provided*	MR		
12	Yard Hydrants.	7 11co-7	Market III (e. )			
14	Total number of hydrants.	Required	Provided*	MR		
mm Si	Hose box.	Required	Provided*	MR		
13	Pumping arrangements.		CALL MADE AND			
15	Ground Level	Provided & Maintained by Mall				
	> Discharge of main pump.	4500 LPM	Provided*	MR		
	Head of main pump.	70 m	Provided*	MR		
	Number of main pumps.	NA NA	Provided*	NA		
	> Jockey Pump output.	180 LPM	Provided*	MR		
	> Jockey Pump head.	70 m	Provided*	MR		
	Standby Pump output.	4500 LPM	Provided*	MR		
	> Standby Pump head.	70 m	Provided*	MR		
V	> Auto Starting/Manual Stopping.	Required	Provided*	MR		
- 4	Pump house access.	Required	Provided*	MR		
	Terrace Level		record mine it is			
	> Discharge of pump.	N/A	N/A	N/A		
	> Head of pump.	N/A	N/A	N/A		
	> Power supply.	N/A	N/A	N/A		
	> Auto starting of pump.	N/A	N/A	N/A		
14	Captive water storage for fire fighting.		ded & Maintained by	Mall		
14	Underground tank capacity.	1,50,000 ltr	Provided*	MR		
	> Draw-off connection.	Required	Provided*	MR		
	Fire Service Inlet.	Required	Provided*	MR		
	Access to tank.	Required	Provided*	MR		
	Overhead tank capacity.	10,000 ltr	Provided*	MR		
15		Required	Provided*	MR		
16	Provision of Lifts.  Required Provided & Maintained by Mall					
10	Pressurization of lift shaft.	N/A	N/A	N/A		
	Pressurization of lift lobby.	N/A	N/A	N/A		
	• Communication in lift car.	N/A	N/A	N/A		
	Fireman's switch.	N/A	N/A	N/A		
-	Lift signage.	N/A	N/A	N/A		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area					
10	Melage Alea	-	eguitor o late 1 - 8			
	Total area	N/A	N/A	N/A		
	• Location	N/A	N/A	N/A		
19	Fire Control Room.		ded & Maintained by			
C.	Detector system panel.	Required	Provided*	MR		
	Flow switch panel.	Required	Provided*	MR		
	PA system panel.	Required	Provided*	MR		
	Battery backup.	Required	Provided*	MR		
	Building floor plan.	N/A	N/A	N/A		
20	Special Fire Protection System for the	NT/A	TATIAL L			
-	Protection of special Risk, if any.	N/A	N/A	N/A		

Note: - \* Fire Fighting arrangement provided & Maintained by D-Mall, Sector 10, Rohini, Delhi.

A



The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the management has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 44 dated 29/01/2025.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2022/WZ/EH/29 dated 04/02/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (NW) - on leave

Today, DO (Mi) Joines hui duty.

Check 4 forward.

04/03/202