

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 NO. F-6/DFS/MS/EH/2025/SZ/ 44 Dated 29/01/2025

To

The Addl. Commissioner of Police, Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049.

Sub: - Regarding issuance of fire safety certificate in r/o M/s Haldiram Products Pvt Ltd, located at 5A, 6, 7, D-Mall, Sector 10, Rohini, Delhi.

Sir,

This has reference to with MCD Portal ID 2025010700225 dated 07/01/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 22.01.2025 in the presence of Mr. Abhishek to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

- 1 The alternative staircase at mezzanine floor found blocked and closed.
- 2 Smoke management system not working.
- 3 Automatic detection system not working.
- 4 MOEFA not working.
- 5 Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

DIRECTOR

DELHI FIRE SERVICE

27/1/0025