

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

F6/DFS/MS/GH/NDZ/2025/ 25.3 No.

Dated: 23/05/2025

To

The Commissioner,

Municipal Corporation of Delhi,

Dr. SPM Civic Centre, New Delhi - 02.

Regarding renewal of Fire Safety Certificate (FSC) in r/o M/s Hare Krishna Guest Sub:

House situated at 1572, Main Bazar, Pahar Ganj, New Delhi - 110055.

Sir.

This has reference to MCD online application ID No.2025050107660 dated 01.05.2025 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 14.05.2025 and observed that the shortcomings intimated vide letter of even No.F.6/DFS/MS/GH/2025/SZ/152 dated 04/04/2025 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building /premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Encl: As above.

Yours faithfully,

Delhi Fire Service

Tel: 011-2341400

Copy to:-

The Manager,

M/s Hare Krishna Guest House at 1572, Main Bazar, Pahar Ganj, New Delhi - 110002.



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/GH/2025/SZ/ 152-

Dated: 04 /04/2025

To

The Joint Commissioner of Police (Licensing) 1st Floor, Police Station Defence Colony, New Delhi 110049

Subject: Regarding issuance of Fire Safety Certificate in r/o M/s Hare Krishna Guest House at 1572-73, Main Bazar, Pahar Ganj Delhi 110055.

Sir,

This has reference with MCD Portal 2025031503581 dated 15/03/2025 on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 27/03/2025 in the presence of Mr. Uma Shankar (Front Office) to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following obscrvations:-

- 1. Smoke ventilation system not provided as per clause 7.31 of UBBL 2016.
- First Aid hose reel hose provided but found not working.
- 3. Terrace level fire fighting pump capacity 225 LPM provided but found not working.
- 4. Exits signage found removed at some places.
- 5. The occupancy above 3rd floor of the building is not allowed as per the clause 7.31 of UBBL 2016.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully.

SERVICE