



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No.F.6/DFS/MS/GH/2025/NDZ/ 356

Dated: 19108/2015

To,

The Owner/Occupier, M/s Hare Krishna Guest House 1572, Main Bazar Pahar Ganj, New Delhi-110055.

Subject:-Regarding issuance of Fire Safety Certificate in r/o M/s Hare Krishna Guest House located at 1572, Main Bazar Pahar Ganj, New Delhi-110055.

Sir,

This has a reference to MCD online application ID No. 2025071711469 dated 17/07/2025 on the subject cited above. In this connection, it is to inform you that officer concerned of this department has visited the premises on dated 08/08/2025 in presence of Sh. Niranjan Rai, Manager and observed that the shortcomings as communicated earlier vide F.6/DFS/MS/GH/2025/SZ/152 dated 04/04/2025 (copy enclosed) have not been complied yet.

In view of above, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire Safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Encl. As above

Copy to:-

MCD online Portal ID-2025071711469



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/GII/2025/SZ/ 152-

Dated: 04 /04/2025

To

The Joint Commissioner of Police (Licensing) 1st Floor, Police Station Defence Colony, New Delhi 110049

Subject: Regarding Issuance of Fire Safety Certificate in r/o M/s Hare Krishna Guest House at 1572-73, Main Bazar, Pahar Gani Delhi 110055. Sir.

This has reference with MCD Portal 2025031503681 dated 15/03/2025 on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 27/03/2025 in the presence of Mr. Uma Shankar (Front Office) to verify the present status of fire safety measures installed in the building. The fire safety arrangements were tested / checked and found following observations:-

1. Smoke ventilation system not provided as per clause 7.31 of UBBL 2016.

2. First Aid hose reel hose provided but found not working.

3. Terrace level fire fighting pump capacity 225 LPM provided but found not working.

4. Exits signage found removed at some places.

5. The occupancy above 3rd floor of the building is not allowed as per the clause 7.31 of UBBL 2016.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully.