

cl49

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/2025/ 299

Dated: 23/06/2025

To

The Sub Divisional Engineer,
Public Health Engineering, Sub Division,
Haryana Bhawan, Copernicus Marg,
New Delhi.

Sub:- Regarding issuance of fire safety certificate in r/o Haryana Bhawan, Copernicus Marg, New Delhi.

Sir,

This has reference to your letter no. nil dated 28.05.2025, on the subject cited above in this regard, it is to inform you that the main block and extension block of Haryana Bhawna was inspected by the officers concerned of this department on 16/06/2025 in the presence of **Sh. Rohtash Kadaula (JE)**, and the following shortcomings were observed:-

1. Fire check door is not provided on alternate staircase of extension block for compartmentation.
2. Hydrant & hose reel found nonfunctional due leakages in pipe line.
3. MCP & PA system found nonfunctional.
4. Pumps not in auto start provision.
5. Draw off connection is not accessible for fire engine.
6. Fire service inlet found non functional
7. Exit signage found inadequate.

In view of above. The FSC cannot be issued till compliance of above shortcomings at the earliest for further consideration in the matter.

Yours faithfully


(Atul Garg)
DIRECTOR
Delhi Fire Service

19/6