## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No.F.6/DFS/MS/2025/ 266

Dated 9/06/2025

To.

Sh. Baldev Dhiman, Hemkunt House, 6, Rajendra Place, New Delhi-110008.

Sub:- Regarding renewal of FSC in r/o Hemkunt House, at Plot No. 06, Rajendra Place, New Delhi-110008.

Sir,

hemkuntassociation@gmail.com dated on the subject cited above. In this connection it is to inform that the site was visited by the officers id concerned of this department on 27/05/2025 in the presence of Manager and the following shortcomings were observed:-

1. Hose reel & Hydrants found nonfunctional.

2. Detector found nonfunctional in some offices and also not provided in second floor.

3. Smoke management system in basement found removed.

4. Sprinklers are not provided at some places in common corridor, required to be extended at left out

5. Fire check door found broken and door closer also found removed.

6. Lift signage's found removed.

In view of above case is rejected with a request to rectify the above shortcomings at the earliest for further consideration in the matter. Further, the occupancy of the building/premises in absence of requisite fire safety arrangements shall be at risk and liability of owner/occupier. The licensing /statuary authority may take suitable necessary action as deemed fit.

Yours faithfully

Virendra Singh Chief Fire Officer Delhi Fire Service

Copy to:-

The Commissioner of MCD, Civic Centre, New Delhi.