



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No.F6/DFS/MS/School/2025/NDZ/57

Dated: 23 01 2025

To,

The Principal, Henry Dunant Public School, D/2-3, Jhilmil Colony, Delhi-110095...

Sub:- Regarding Issuance Fire Safety Certificate r/o Henry Dunant Public School, at D/2-3, Jhilmil Colony, Delhi-110095.

Sir,

With reference to your letter Nil dated 25/11/2024 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence Principal on dated 09/01/2025. During the inspection it as communicated earlier vide shortcomings that the was F.6/DFS/MS/School/2012/4312 dated 19/11/12 have not been complied yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Encl .: - as above

Yours faithfully

Copy to:-

The Dy. Director of Education D-Block, Anand Vihar, Delhi-110053

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/ms/school/2012/4312

Dated: 19/11/12

₹o,

The Principal,
Henry Dunant Public School,
D/2-3, Jhilmil Colony, Delhi-95.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Henry Dunant
Public School, D/2-3, Jhilmil Colony, Delhi-95.

Sir.

Please refer to your letter No. IRCS/HDPS/2012-2013 dated 25.10.12 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the rule 33 of the Delhi Fire Service Rules, 2010. At the time of inspection Mr. S.K.Sharma, Executive Officer was present and observed that the school building is comprised of ground plus three upper floors only. During the course of inspection, it was also noticed that-

- An additional staircase is required.
- Hose reel is not provided at each floor level, this same shall be provided.
- 3. Over head water storage tank 10,000 liters capacity is not found provided at terrace.
- 4. Fire pump having 450 LPM out put at 40 m head is not found provided at terrace.
- 5. Exit signs are not found provided.

Due to which the building cannot be considered for issuance of Fire Safety Certificate.

Yours faithfully

(DR. T.S. SHARMA)

Dy. Chief Fire Officer (NDZ)

Delhi Fire Service

Copy to: -.

The Joint Director of Education (Land & Estate) Directorate of Education, Lucknow Road, Delhi -54.