

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001



No. F.6/DFS/MS/WZ/Educational/2025/310

To,

Mr. Rajeev Kumar, Indian Institute of Technology. Institute Engineer Indian Institute of Delhi. Gauz Khas, New Delhi-110016.

Sub: Issue of FSC in r/o M/s I.T. School, 90Ph2 & Hi-Tech-IT School Campus, IIT Delhi, Hauz Khas, New Delhi.

Sir,

This is refer to online application no. 10108128 dated 10.06.2025, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on 19.05.2025, in presence of Mr. Praveen Kumar (J.E) to ascertain the availability and operability of the fire prevention and fire safety measures. The following shortcomings were observed:

1. Alternate staircase is not provided in basement.

2. Staircases are neither pressurization nor suitably ventilated.

3. First Aid hose reel & FHC not provided in basement.

4. Some sprinkler heads on found obstructed due to service ducts.

5. Terrace Fire pump not found in auto mode.

In this regard as stipulated in sub Rule (5) of Rule 35 of DFS Act-2007 & Rules 2010 it is advised the applicant to apply with a fresh application for grant of fire safety certificate under sub-rule (2) on Form "I"/MCD Portal and it shall be accompanied with a certificate from the architect and owner or occupier that all the fire prevention and fire safety measures are duly complying with the requirements as communicated under sub-rule (4) above, for further consideration in this regard. The web links for DFS Act-2007/ Rules 2010 & Form "I" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http:// www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms

Yours faithfu

Copy To:-

MCD Request ID.10108128 dated 10.06.2025.