



75
Azadi Ka
Amrit Mahotsav

C/96

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/CGHS/2025/SZ / 454

Dated: 21 / 03 / 2025

To

Dr. Col. Ashwini Kumar,
President, Hind CGHS Ltd,
Plot No. 12, Sector-5,
Dwarka, New Delhi-110075

Sub: Regarding renewal of Fire Safety Certificate in r/o "Hind CGHS Ltd" located at Plot No. 12, Sector-5, Dwarka, New Delhi-110075

Sir,

This has reference to your letter No. 5492/Fire NOC/Hind dated 06/02/2025 received through outdoor diary No. 12290 dated 10/02/2025, on the subject cited above. In this connection, it is to inform you that the premise was visited by the officer concerned of this department on 12/03/2025 in the presence of Sh. Sandeep Kumar (Manager) to verify the compliance of the shortcomings communicated by this office vide letter No. F6/DFS/MS/CGHS/SZ/2023/1056 dated 22/05/2023 and observed that the shortcomings are still not fully complied.

In view of the above, application for renewal of fire safety certificate is rejected. You are directed to rectify the shortcomings in toto as early as possible under intimation to this department for further action in the matter.

Yours faithfully,

(Atul Garg)
DIRECTOR

T. No. 011-23414000

Copy to: -

1. The Commissioner, Municipal Corporation of Delhi, 8th Floor, Civic Centre, JLN Marg, New Delhi-110002

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

C-127

No.F6/DFS/MS/S7/CGHS/2023/ 1056

Dated 22/05/2023

To,

The President,
Hind CGHS Ltd.
Plot No. 12, Sector - 05, Dwarka,
New Delhi - 110075

Subject: Renewal of Fire Safety Certificate in r/o Hind CGHS Ltd. Located at Plot No. 12, Sector - 05, Dwarka, New Delhi - 110075.

Sir,

This is in reference to your letter No. nil, dated-05/05/2023 on the subject cited above. In this connection it is to inform to you that the above said residential building has been inspected by the officer concerned of this department on 16/05/2023 in presence of Sh. Sandeep (Manager) from fire safety point of view.

During course of inspection the following shortcomings are observed.

1. Trimming of trees/ encroachment must be removed to ensure free movement of fire vehicles around the building.
2. Hose Reels & Hydrants system found nonfunctional
3. Terrace pump having capacity 450 lpm found nonfunctional and the pump must be kept in auto mode.
4. Manual call point found non functional.
5. Public Address System found nonfunctional
6. Exit signage found removed at some places.
7. Hoses, Branches & couplings are found removed at some places.
8. Communication system in the lift car found removed.
9. Dully filled form J & K are not submitted.

You are requested to comply the abovementioned shortcomings under intimation with this department.

In view of the above shortcomings renewal of Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

(Atul Garg)
Director

Delhi Fire Service

Copy to; - The Joint Director, DDA, Vikas Sadan, INA, New Delhi.