



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/CGHS/2025/SZ/722

Dated: 06 /05 /2025

To

Mrs. Nirmal Malhotra, Secretary, Hind CGHS Ltd, Plot No. 12, Sector-5, Dwarka, New Delhi-110075

Sub: Regarding renewal of Fire Safety Certificate in r/o "Hind CGHS Ltd" located at Plot No. 12, Sector-5, Dwarka, New Delhi-110075

Sir,

This has reference to your letter No. 5492/Fire NOC/Hind dated 19/03/2025 received in this department vide outdoor diary No. 14825 dated 21/03/2025, on the subject cited above. In this connection, it is to inform you that the said residential complex was visited by the officer concerned of this department on 24/04/2025 in the presence of Sh. Sandeep Kumar (Manager) to verify the compliance of the shortcomings communicated vide this office letter No. F6/DFS/MS/CGHS/SZ/2023/1056 dated 22/05/2023 and observed that the shortcomings are still not fully complied.

In view of the above, application for renewal of fire safety certificate is rejected. You are advised to rectify the shortcomings in toto as early as possible in the interest of public safety, under intimation to this department for further action in the matter.

Yours faithfully,

DIRECTOR

14

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No.F6/DFS/MS/SZ/CGHS/2023/ /056

Dated 22 /05/2023

To,

The President, Hind CGHS Ltd. Plot No. 12, Sector - 05, Dwarka, New Delhi - 110075

Subject: Renewal of Fire Safety Certificate in r/o Hind CGHS Ltd. Located at Plot No. 1,2, Sector - 05, Dwarka, New Delhi - 110075.

This is in reference to your letter No. nil, dated-05/05/2023 on the subject cited above. Sir, In this connection it is to inform to you that the above said residential building has been inspected by the officer concerned of this department on 16/05/2023 in presence of Sh. Sandeep (Manager) from fire safety point of view.

During course of inspection the following shortcomings are observed.

- 1. Trimming of trees/ encroachment must be removed to ensure free movement of fire vehicles around the building.
- 2. Hose Reels & Hydrants system found nonfunctional
- 3. Terrace pump having capacity 450 lpm found nonfunctional and the pump must be kept in auto mode.
- 4. Manual call point found non functional.
- 5. Public Address System found nonfunctional
- 6. Exit signage found removed at some places.
- 7. Hoses, Branches & couplings are found removed at some places.
- 8. Communication system in the lift car found removed.
- 9. Dully filled form J & K are not submitted.

You are requested to comply the abovementioned shortcomings under intimation with this department.

In view of the above shortcomings renewal of Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

li Fire Service